ORAU Team NIOSH Dose Reconstruction I	Document Number: ORAUT-TKBS-0006-2 Effective Date: 10/02/2003		
Technical Basis Document for the Hanford Site Site			Revision No.: 00 Controlled Copy No.: Page 1 of 38
Subject Expert: Jack Selby	to the second se		Supersedes
Approval: C	Date:	10/3/03	
Approval: Signatures on file.	Date:	10/3/03	None
Concurrenc	Date:	77	
Approval: James W. Neton, OCAS Health Sci	Date: ence Adminis	/0/3/03 strator	

### **TABLE OF CONTENTS**

Sec	<u>tion</u>		<u>Pag</u>	<u>ge</u>
Rec	ord of Is	ssue/Revisions		5
Acro	onyms a	and Abbreviations	·••••	6
Han	ford Site	e Description and Processes		7
2.1	React	ors		. 7
	2.1.1	105-B, C, D, DR, F, H, KW, and KE Production Reactors		
	2.1.2	105-N Production Reactor		
	2.1.3	305 Hanford Test Reactor		
	2.1.4	305-B Physical Constants Test Reactor		
	2.1.5			
	2.1.6	309 Plutonium Recycle Test Reactor		. 9
	2.1.7	309 Plutonium Recycle Critical Facility		. 9
	2.1.8	318 High Temperature Lattice Test Reactor		. 9
	2.1.9	405 Fast Flux Test Facility	•••••	. 9
	Fuel S	Separations Facilities		10
	2.2.1	Original Fuel Separations Facilities		10
	2.2.2			
	2.2.3	202-A PUREX Plant		11
	2.2.4			11
	2.2.5	224-U UO <sub>3</sub> Plant	,,,,,,,,	12
	2.2.6	225 Waste Encapsulation and Storage Facility	'	12
	2.2.7	201-C C Plant or Hot Semiworks		12
	2.2.8	400 B T W		
	Fuel F	abrication Facilities		12
		313 Uranium Metal Fuels Fabrication Facility		

	2.3.2	314 Uranium Metal Extrusion Facility	13
	2.3.3	333 Fuel Cladding Facility	
	2.3.4	306 Reactor Fuel Manufacturing Pilot Plant	
	2.3.5	303 Facilities Fresh Metal Storage Facilities	14
2.4		ium Finishing Facilities	
	2.4.1	231-Z Plutonium Isolation Facility	14
		234-5Z Plutonium Finishing Plant Complex	
		2.4.2.1 Rubber Glove Line	
		2.4.2.2 Remote Mechanical A Line	15
		2.4.2.3 Remote Mechanical C Line	
		2.4.2.4 Recovery of Uranium and Plutonium by Extraction Facility	
		2.4.2.5 232-Z Incinerator Facility	16
		2.4.2.6 236-Z Plutonium Reclamation Facility	16
		2.4.2.7 242-Z Waste Treatment Facility	17
	2.4.3	Plutonium Storage Facilities	17
2.5	Resea	rch, Development, and Testing Facilities	17
	2.5.1	108-F Biology Facility	
	2.5.2	120 Critical Mass Laboratory Facility	
	2.5.3	209-E Critical Mass Laboratory	18
	2.5.4	222-B Laboratory	18
	2.5.5	222-S Laboratory	18
	2.5.6	222-T Laboratory	18
	2.5.7	308 Plutonium Fuels Pilot Plant	
	2.5.8	318 Radiological Calibration and Development Laboratory	19
	2.5.9		
	2.5.10	321 Separation Facility	19
	2.5.11	324 Chemical and Materials Engineering Laboratory	19
		325 Radiochemistry Laboratory	
	2.5.13	326 Pile Physics Technology and Metallurgy Facility	20
		327 Radiometallurgy Laboratory Facility	
		329 Biophysics Laboratory	
		331 Life Sciences Laboratory Facility	
		3706 Radiochemistry Laboratory	
	2.5.18	3730 Gamma Irradiation Facility	21
	2.5.19	3732 Process Equipment Development Laboratory	22
	2.5.20	3741 Graphite Hot Shop Facility	22
	2.5.21	3745 Radiological Calibrations and Standards Laboratory	22
2.6	Waste	Handling Facilities	22
	2.6.1	High-Level Liquid Waste Tanks	
	2.6.2	216-Z-9 Trench Facility	23
		241-Z Settling Tank	
	2.6.4	242 Evaporator Facilities	23
	2.6.5	Chemical Separations Exhaust Filtration Facilities	24
	2.6.6	340, 340-A and 340-B Liquid Waste Handling Buildings	
Refe	erences		25
Glos	sarv		27

Effective Date: 10/02	2/2003 Revision No. 0	Document No. ORAUT-TKI	3S-0006-2 Page 3 of 38
Attachment A – Des	scription of Facilities a	and Processes	28

Effective Date: 10/02/2003 Revision No. 00 Document No. ORAUT-TKBS-0006-2 Page 4 of 38

### LIST OF TABLES

<u>Table</u>		<u>Page</u>
2.4.1-1	Plutonium nitrate processing tasks	15
	Exhaust filtration facilities	

tive Date: 10/02/2003   Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 5 of 38
---	--------------------------------	--------------

### **RECORD OF ISSUE/REVISIONS**

ISSUE AUTHORIZATION DATE	EFFECTIVE DATE	REV. NO.	DESCRIPTION
DRAFT	10/02/2003	00-A	New document to establish the Hanford Facilities and Processes, Section 2, TBD. Initiated by Edward D. Scalsky.
10/02/2003	10/02/2003	00	First approved Issue of Revision 00. Initiated by Edward D. Scalsky.

Document No. ORAUT-TKBS-0006-2	Page 6 of 3
--------------------------------	-------------

### 1 ACRONYMS AND ABBREVIATIONS

Effective Date: 10/02/2003 Revision No. 00

2	Burnup	Depletion of fissionable material i.e., 235Pu
3	CEDE	Committed Effective Dose Equivalent
4	D&D	Decontamination and Decommission
5	EBR II	Experimental Breeder Reactor II
6 7	FP FFTF	Fission Products Fast Flux Test Facility
8	GETR	General Electric Test Reactor
9 10 11	HTLTR HTR kVp	High Temperature Lattice Test Reactor High Temperature Reactor kiloVolt potential
12 13 14 15	MeV MW Mint MTR	Million electron Volts Megawatts Tritium Materials Test Reactor
16 17 18 19 20 21 22 23 24 25 26	P-10 PCTR PFP PFPP Pile Pit PNNL PRCF PRF PRTR PUREX	Tritium Physical Constants Test Reactor Plutonium Finishing Plant Plutonium Fuels Pilot Plant Reactor A machined part of a nuclear weapon Pacific Northwest National Laboratory Plutonium Recycle Critical Facility Plutonium Reclamation Facility Plutonium Recycle Test Reactor Plutonium-Uranium Extraction Plant
27 28	QA QC	Quality Assurance Quality Control
29 30 31 32 33	RECUPLEX REDOX RG RMA RMC	Recovery of Uranium and Plutonium by Extraction Reduction Oxidation Plant Rubber Glove Remote Mechanical A Line Remote Mechanical C Line
34	Slugs	Another name for fuel elements
35	TRIGA	Training Research Isotopes, General Atomics Reactor
36	TTR	Thermal Test Reactor

Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 7 of 38

### 1 HANFORD SITE DESCRIPTION AND PROCESSES

- 2 Construction of facilities at the Hanford Site, an area of approximately 600 square miles, commenced
- 3 in Mar. 1943 when several major nuclear facilities were started. These included 105-B (Production
- 4 Reactor); 221-T (Separation Facility); 305 (Test Pile); and 313 (Fuel Element Fabrication). The
- 5 production reactors designed to produce plutonium by irradiating metallic uranium, were constructed
- 6 in the 100 Areas located along the Columbia River on the north side of the Hanford site. The
- 7 separation facilities were built in the 200 Areas located on a high plateau in the center of the Hanford
- 8 Site. The fuel fabrication facilities, test reactors and research and development laboratories were built
- 9 in the 300 Area located on the south side of the Hanford Site. The facilities discussed in subsequent
- 10 sections represent those facilities out of more than 500 major facilities where nuclear activities were
- 11 conducted. Note: Throughout this document, where a "\*" is included with a date this indicates either
- there were two dates found (the most claimant-favorable was listed) or the actual year in the decade
- was not found in the documents. Where "UNK" is used, a date has not been found.

#### 2.1 REACTORS

- Nine-graphite-moderated, light water cooled reactors were constructed near the Columbia River in the
- Hanford 100 Areas over a period of 20 years commencing in 1943 (Carlisle, 1996). The production
- 17 reactors were used to produce plutonium by irradiating metallic uranium fuel elements with neutrons
- during the fission reaction in the reactor core. Other defense-related radionuclides that were
- experimented with included: irradiation of thorium to produce <sup>233</sup>U, irradiation of depleted uranium to
- 20 produce <sup>240</sup>Pu, irradiation of neptunium targets to produce <sup>238</sup>Pu, and irradiation of americium to
- 21 produce medical grade <sup>238</sup>Pu. These nine production reactors designated 100-B, C, D, DR, F, H, KW,
- KE, N were constructed in the B, D, F, H, K, and N Areas, respectively from 1944 to 1963. The first
- eight reactors at Hanford designated 105-B, C, D, DR, F, H, KW, and KE were similar in design
- 24 utilizing a once-through light-water cooling system. The ninth reactor, 105-N, utilized a closed-loop
- 25 light water cooling system. The years of operation and radionuclides of concern are shown in Tables
- A.1-1 and A.1-2 respectively in appendix A. External exposures are primarily due to the presence of
- 27 activation and fission products (FP). During operation, entry was controlled into areas where high
- 28 direct dose rates from photons and neutrons could occur. Internal exposures involving uranium,
- 29 activation products, and fission products, were primarily limited to maintenance and refueling
- 30 activities.

39

14

- 31 Additionally, there were seven physical testing, research and demonstration reactors operated at
- 32 Hanford over a period of 40 years (Carlisle, 1996). Six Research and Test Reactors, located in the
- 33 300 Area were constructed and operated from 1943 to 1978. These include the 305 Hanford Test
- Reactor (HTR), Physical Constants Test Reactor (PCTR), Thermal Test Reactor (TTR), Plutonium
- 35 Recycle Test Reactor (PRTR), Plutonium Recycle Critical Facility (PRCF), and High Temperature
- 36 Lattice Test Reactor (HTLTR) (Newman, 1989). The Fast Flux Test Facility (FFTF Reactor) was
- 37 constructed and operated from 1980 to 1993 in the 400 Area. The years of operation and
- radionuclides of concern are shown in Tables A.1-3 and A.1-4 in Appendix A.

### 2.1.1 105-B, C, D, DR, F, H, KW, and KE Production Reactors

- 40 The first three reactors (100-B, D, and F) were built in B, D, and F Areas starting in Aug, Nov. and
- 41 Dec. 1943. The B reactor commenced operation in Sept. 1944. The D and F Reactors commenced
- 42 operation in Dec. 1944 and Feb. 1945 respectively. In addition to producing plutonium for nuclear
- 43 weapons, the reactors also produced polonium for use as a neutron source trigger or initiator in the
- 44 weapons. By May 1945 four of the tubes in D Reactor were charged with bismuth slugs for polonium
- 45 production. Construction of DR Reactor, located in D Area, was started in Dec. 1947 with startup

Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 8 of 38

- 1 commencing in Oct. 1950. The H Reactor was constructed in H Area starting in Mar. 1948 with
- 2 startup in Oct. 1949. Construction of C Reactor in B Area commenced in Jun 1951 with startup in Nov
- 3 1952. The KW and KE Reactors were constructed in KW and KE Areas starting in Nov. 1952 and
- 4 Jan. 1953. They commenced operation in Dec. 1954 and Feb. 1955 respectively. These eight
- 5 reactors were graphite moderated and single pass cooled using treated river water. The first three
- 6 reactors (B, D and F) were the same design. The remaining five reactors (DR, H, C, KW and KE)
- 7 were similar in design with the KE and KW reactors differing primarily in the number, size and type of
- 8 process tubes, the size of the graphite stack, and the type of shielding.
- 9 The fuel elements were metallic uranium clad with aluminum. In 1960, confinement systems were
- incorporated in the first eight reactors and these reactors were shut down over a period of years
- starting in 1964 and ending in 1971. See Table A.1-1 for shutdown dates.

### 12 **2.1.2 105-N Production Reactor**

- 13 Construction of 105-N (ninth production reactor) was started in N Area in 1959. The N Reactor design
- was based on the original graphite production reactors. However, it differed substantially from the first
- eight since it incorporated closed-loop cooling and it was the first Hanford reactor to incorporate a
- 16 confinement system in the original design. It was designed to be a dual-purpose reactor (i.e.
- 17 producing both plutonium and steam to be used to generate power). The dual-purpose reactor
- started producing plutonium in Mar. 1964 and electrical power some time later. The N reactor fuel
- was a tube-in-tube design consisting of a metallic uranium core surrounded by a thin zircaloy-2
- 20 cladding. The core consisted of an inner tube enriched to 0.95% U-235 and an outer tube enriched to
- either 0.95% or 1.25% U-235. From 1965 to 1967, tritium was produced at N-Reactor using fuel
- 22 elements manufactured in the 333 facility. The N reactor was shut down in 1987.

#### 23 2.1.3 305 Hanford Test Reactor

- 24 The 305 Hanford Test Reactor (HTR) (also called the Test Pile) located in the 305 Building was the
- 25 first reactor to operate at Hanford starting in 1943. It was operated until 1972 at a very low critical
- level (usually less than 50 W) to test fuel elements, fuel configuration, graphite samples and other
- 27 materials for the production reactors. It was used as a quality assurance tool to house testing of
- samples of each lot of graphite, uranium, aluminum jacketing material, and other materials used in the
- 29 large production reactors. The reactor consisted of a graphite pile and was air-cooled. It was
- removed from the 305 building in 1976-1977.

### 31 2.1.4 305-B Physical Constants Test Reactor

- 32 The Physical Constants Test Reactor (PCTR) started operation in 1954. The 800 W test reactor was
- 33 located in a shielded room in the 305-B building. The mission of the PCTR was to measure reactor
- 34 changes as a result of use of different reactor fuels. Some plutonium contamination that occurred in
- 35 the reactor room as a result of an accident could have been the source of minor internal exposure
- 36 during cleanup. External exposure was negligible since the reactor was located in a shielded
- 37 underground room and operated remotely. Operation was terminated in 1970.

#### 2.1.5 305-B Thermal Test Reactor

- 39 The Thermal Test Reactor (TTR) started operation in 1954. The 1 KW reactor was located in a
- 40 shielded underground room in the 305-B building and operated remotely. The mission of the TTR
- 41 was to measure thermal impact on fission cross sections. It functioned as an early and small version

Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 9 of 38
----------------------------	-----------------	--------------------------------	--------------

- 1 of the HTLTR. External exposure was minimized since the reactor was operated remotely. Operation
- 2 was terminated in the 1978.

3

### 2.1.6 309 Plutonium Recycle Test Reactor

- 4 The Plutonium Recycle Test Reactor (PRTR), located in the 309 building, started operating in 1960.
- 5 The PRTR was a 40 MW heavy-water-cooled and heavy-water-moderated reactor. The reactor was
- 6 chosen for a large fuels diversification program known as the Plutonium Fuels Utilization Program.
- 7 Tests were to be performed with various mixed oxide fuels using various methods of manufacture. As
- 8 an example, tests were performed on a variety of powdered and pelletized fuels using plutonium oxide
- 9 blended with uranium oxide and other metallic oxides. The fuel was a nominal 96% depleted uranium
- oxide and 4% plutonium oxide powder that was vibration compacted within the fuel pin. External
- 11 exposure was minimized as a result of the remote operation and the shielding. Maintenance
- 12 operations resulted in external exposure from activation and fission products. A high extremity
- 13 exposure occurred when a worker picked up an irradiated steel pin. Tritium (<sup>3</sup>H) oxide was the
- principal internal exposure contaminant during normal operation. This whole body exposure was
- added into the external whole body dose summary (See sections 5 and 6 Internal and External
- Dosimetry). The reactor was shutdown in 1969 after an accident resulted in contamination in the
- Dosinetry). The reactor was shutdown in 1969 after an accident resulted in contamination in the
- reactor. A sample of the contamination showed the major contaminant was <sup>95</sup>Zr/Nb. Other contaminants included <sup>60</sup>Co, <sup>103</sup>Ru, <sup>106</sup>Ru, <sup>106</sup>Rh, <sup>140</sup>Ba/La, <sup>141</sup>Ce, <sup>144</sup>Ce, and <sup>144</sup>Pr.
- 19 2.1.7 309 Plutonium Recycle Critical Facility
- 20 The Plutonium Recycle Critical Facility (PRCF), which was located in the 309 building, began
- 21 operating in 1962. Tests were conducted in the PRCF to determine which geometrical arrangement
- 22 of fissionable materials would work in a reactor. It was shut down in 1976.

#### 23 2.1.8 318 High Temperature Lattice Test Reactor

- 24 The High Temperature Lattice Test Reactor (HTLTR) was a 2 MW test reactor built in the 318 building
- in 1967 with operation commencing in 1968. The reactor consisted of a graphite cube located in a
- large shielded room and was operated at elevated temperatures up to 1000°C. The mission was to
- 27 advance reactor physics technology. It was shut down in 1971 after 3-years of operation spanning 4
- years during which time they operated with six different cores (i.e. three <sup>233</sup>U, one <sup>235</sup>U, one <sup>238</sup>U,
- and one <sup>239</sup>Pu). Since the reactor was heavily shielded and operated remotely, external exposure
- 30 was at background levels. There were no contamination incidents so internal exposure was
- 31 negligible. The building and the shielded room were modified in the early 1980's and used as the new
- 32 Hanford Radiation Calibration Facility (see section 2.5.8).

### 2.1.9 405 Fast Flux Test Facility

- 34 The Fast Flux Test Facility (FFTF) was a 400 MW sodium-cooled test reactor located in the 405
- building. It began start-up operations in Feb. 1980 in support of the fast breeder reactor program.
- 36 The FFTF was used to test the irradiation of fuels and materials that would be used in a breeder
- 37 reactor and to perform long-term testing of reactor components and systems. It was also used for the
- 38 production of Medical Isotopes and research on space power systems. The external and internal
- 39 exposures were at background levels. The facility was shutdown in 1994 and currently is waiting
- 40 D&D.

Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 10 of 38

#### 1 2.2 FUEL SEPARATIONS FACILITIES

- 2 Seven separation facilities, B Plant, T Plant, U Plant, Reduction/Oxidation (REDOX), Plutonium-
- 3 Uranium Extraction Facility (PUREX), UO<sub>3</sub> and C Plant, were constructed and operated in the 200-W
- 4 and 200-E Areas from 1943 to 1993. The tritium processing facility was operated from 1949 to 1955
- 5 in the 108-B building located in the 100-B Area. Natural uranium and thorium fuel elements and
- 6 lithium-aluminum (Li-Al) target elements were irradiated to produce Pu-239, U-233, and tritium,
- 7 respectively. The spent reactor fuel was transported to the 200 Areas (i.e. Separations Areas) for
- 8 processing. Initially spent fuel was stored in the reactor storage basins and the 212-N, 212-P, and
- 9 212-R buildings in the 200-N Area prior to processing in the fuel separations facilities (e.g.221-B 221-
- 10 T, REDOX and PUREX). The irradiated lithium-aluminum target elements were transferred to the
- 11 108-B building, 100-B Area for processing. Irradiated thorium fuel elements were processed in the
- 12 PUREX Plant to recover U-233 in two separate campaigns that occurred in 1966 and 1971. External
- exposures were primarily high-energy betas and photons in the separations facilities associated with
- 14 fission products (FP). Internal exposures, primarily associated with contamination incidents, could be
- due either to FP and/or plutonium. The years of operation and radionuclides of concern are shown in
- 16 Tables A.2-1 and A.2-2 respectively in Appendix A.

### 2.2.1 <u>Original Fuel Separations Facilities</u>

- Three large canyon buildings 221-T, 221-B and 221-U were originally constructed in the 200 Area in
- 19 1943 (?) to chemically separate plutonium from uranium and fission products. These buildings were
- 20 massive rectangular canyons that housed the chemical separations equipment. This equipment was
- 21 operated remotely to provide protection to the workers from the high radiation fields. The T Plant was
- started up Dec. 1944 and shutdown Aug. 1956 while B Plant started up in Apr. 1945 and shutdown in
- 23 Oct. 1952. Since the capacity was not needed, the start up of U Plant was delayed until 1952 when
- 24 the mission was changed (see section 2.2.4). The 221-T and 221-B buildings known as the T and B
- 25 Plants utilized a bismuth phosphate precipitation batch process to separate plutonium from the
- 26 uranium and fission products after the aluminum jackets were dissolved in sodium hydroxide solution
- 27 and the uranium metal slugs were dissolved in nitric acid. The dilute plutonium solution from T and B
- 28 plants was transferred to the 224 Concentration Buildings (e.g.224-B and 224-T) located behind each
- 29 canyon building where the product was purified, the product volume was reduced and the carrier was
- 30 changed from bismuth phosphate to lanthanum fluoride. The final plutonium product was
- 31 concentrated in the 231-Z Building. The B Plant was closed in 1952. Starting in 1954 and 1955, the
- 32 processing capacity was increased in both facilities. The 221-B and 221-T plants were not restarted
- 33 because of the success of PUREX.
- In March 1956 221-T was converted to perform equipment decontamination (WHC-MR-0452). In
- 35 1959 the 2706 T Decon Annex was added to the 221-T building to enhance the equipment
- decontamination capabilities, particularly pieces of equipment too large to take into T-Plant. The T-
- 37 Plant is still in operation.

- The B Plant facilities were modified in 1968 to remove <sup>90</sup>Sr and <sup>137</sup>Cs from high-level wastes from the
- 39 single and double-shell waste tanks. This was in support of a new mission "to isolate the longer-lived
- 40 fission products by fractionalization for storage in a safer form and to return the short-lived fractions to
- 41 underground storage and ultimate solidification". The purified <sup>90</sup>Sr and <sup>137</sup>Cs solutions were
- 42 transferred to the 225-B Waste Encapsulation Storage Facility (see section 2.2.6). The 221-B
- 43 operated from 1968 to 1978 in support of this new mission.

	Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 11 of 38
--	----------------------------	-----------------	--------------------------------	---------------

#### 2.2.2 1 202-S REDOX Plant

- 2 Construction of the REDOX Facility (S Plant) was started in 1949. In Jan. 1952, REDOX started up in
- the 200-W Area utilizing the REDOX (i.e. reduction/oxidation process) as a replacement for the 3
- 4 bismuth phosphate process. This new REDOX process differed from the process used in B and T
- 5 Plants in that with the exception of the metal dissolving and feed preparation steps, all steps were
- 6 continuous rather than batch. The new process, which involves solvent extraction utilizing hexone,
- 7 resulted in improved throughput, recovery of uranium, improved recovery of plutonium and a decrease
- in the amount of high-level liquid waste generated. The aqueous plutonium product was concentrated 8
- 9 for shipment to the plutonium finishing facilities. In 1950\* processing of irradiated 94 metals (0.947
- 10 enrichment) was assigned to REDOX. Shutdown of this facility occurred in Dec. 1967.
- 11 In an effort to enhance production capacity, the 233-S building was constructed in 1957 to contain the
- 12 third and final concentration cycle at 202-S. This building was shut down in July 1967 after a major
- 13 fire resulted in extensive plutonium contamination. The facility is currently undergoing
- decontamination and decommissioning. 14

#### 2.2.3 15 **202-A PUREX Plant**

- 16 Construction of the PUREX Facility (A Plant) commenced in 1953. It was started up in Jan. 1956
- 17 utilizing the plutonium-uranium extraction process (WHC-MR-0437: Marceau, 2002). The PUREX
- 18 process was an organic solvent extraction process that utilizes tributyl phosphate in kerosene instead
- 19 of hexone, nitric acid as a salting agent, pulse column contractors, and nitric acid recovery by
- 20 distillation. The nominal design capacity was 8.33 short tons uranium per day as opposed to 2.5 for
- 21 the REDOX Plant. In 1955 due to the development of more restrictive 131 release limits the 293-A
- facility was constructed between PUREX and the 291 A stack. In 1958 PUREX initiated <sup>237</sup>Np 22
- recovery activities. Equipment was added in 1962 to permit continuous recovery of <sup>237</sup>Np. In 1963 the processing of e-metal fuel containing <sup>235</sup>U enriched to 1.75 %. The processing of irradiated powdered thorium oxide targets to recover <sup>233</sup>U commenced in 1965 and 1966. In 1970 the targets were 23
- 24
- 25
- changed to pelletized thorium oxide. The PUREX Plant was shutdown in June 1972 and restarted in 26
- 27 Nov. 1983. During the shutdown a new process was added to convert plutonium nitrate to plutonium
- oxide. It was started-up and shutdown several times between 1983 and 1992 with final closure 28
- 29 announced in Dec. 1992.
- 30 A 500-foot railroad tunnel that extended south from PUREX was designed and constructed to permit
- 31 the remote storage of highly contaminated processing equipment. In 1964 a new 1500-foot tunnel
- was added to PUREX to accommodate the storage of additional equipment. 32

#### 33 2.2.4 **221-U U Plant**

- 34 As noted in section 2.2.1 above, the U Plant was constructed in 1943. The U Plant startup was
- 35 delayed until Mar. 1952 when it was reconfigured for use in recovering uranium from process waste.
- 36 The high-level liquid wastes from the B and T Plants, which were stored in single-shell tanks,
- 37 contained large quantities of uranium. The uranium bearing sludge from the underground storage
- 38 tanks was pumped to process vessels in the U Plant. The sludge was dissolved in nitric acid and the
- 39 uranium extracted by solvent extraction using tributyl phosphate in kerosene. The recovered Uranium
- 40 was shipped off-site for reuse. The U Plant was shutdown in Jan. 1958.

	Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 12 of 38
--	----------------------------	-----------------	--------------------------------	---------------

### 1 2.2.5 <u>224-U UO<sub>3</sub> Plant</u>

- 2 The 224-U Bulk Reduction Building (known as UO<sub>3</sub> Plant) was constructed in the 1940's. In 1951 it
- 3 was converted to process the liquid uranium nitrate solution from U Plant to produce a powdered
- 4 uranium oxide (UO<sub>3</sub>) using a calcination process. It was started up in Jan. 1952. The product was
- 5 shipped off-site for reuse. A major addition (224 UA) was added to the UO<sub>3</sub> Plant in the fourth quarter
- 6 1956 to house 3 new calciners. It was shutdown in 1972 and opened again in 1983 (there were 17
- 7 start ups and shutdowns between 1984 and 1992 corresponding to activities at PUREX) and was
- 8 deactivated in the summer of 1993.

### 9 2.2.6 225 Waste Encapsulation and Storage Facility

- 10 The 225-B Waste Encapsulation and Storage Facility is located in the 200-E Area near the 221-B
- Building. In 1979\* as a part of the effort to "isolate the longer-lived fission products from high-level
- waste tanks the <sup>137</sup>Cs and <sup>90</sup>Sr solutions were transferred to the 225-B from 221-B for conversion to a
- solid, encapsulation, and storage (see section 2.2.1 for more details). A large amount of
- encapsulated <sup>137</sup>Cs and <sup>90</sup>Sr was stored in the 225 Building as a result of this operation. External
- exposures that were associated with the high- energy photons and beta particles from the large
- 16 quantities of strontium and cesium processed were minimized as a result of remote operation.
- 17 Internal exposures from the operation were minimal due to the remote operation.

### 18 2.2.7 <u>201-C C Plant or Hot Semiworks</u>

- 19 The Hot Semiworks (also known as hot sloppy) started up in 1949 as a pilot plant (Marceau, 2002) to
- 20 develop REDOX reprocessing technologies. The REDOX process was tested in the 201-C
- 21 reprocessing pilot plant starting in 1952, with work continuing until 1954. In 1954, the C Plant was
- switched to being the PUREX process pilot plant and was shutdown in 1956. In 1962, C Plant was
- restarted as a pilot plant for the recovery of Cs and Sr from fission product waste. The C Plant was
- 24 retired in 1967.

### 25 2.2.8 108-B Tritium Extraction Facility

- 26 The 108-B building (known as P-10 Plant and also the Mint Works) located in the 100-B Area started
- 27 in Aug. 1944 to extract tritium. The Li-Al (for a short period lithium fluoride) target elements were
- 28 transferred to the 108-B facility after irradiation in one of the production reactors. Tritium extraction
- 29 operations were performed intermittently between Aug. 1949 and 1955. The 108-B tritium operation
- was terminated in 1955. The Li-Al target irradiation was continued with transportation to an offsite
- 31 facility for processing until Sep, 1964. A total of 10.6 kg of tritium was produced at Hanford. Internal
- 32 exposure was related to tritium (<sup>3</sup>H). This whole body exposure was added to whole body dose
- 33 summary (See sections 5 and 6 External and Internal Dosimetry).

#### 34 2.3 FUEL FABRICATION FACILITIES

- 35 The Hanford Fuel Fabrication facilities described in subsequent sections were built and operated in
- 36 the 300 Area from 1944 to 1988. These include three fuel fabrication facilities, 313 (Uranium Metal
- 37 Fuels Fabrication), 314 (Uranium Metal Extrusion), and 333 (Fuel Cladding) buildings, and two
- 38 support facilities, 303 (Uranium Storage and Oxide Burner), and 306 (Reactor Fuel Manufacturing
- 39 Pilot Plant). External exposures were related to betas and photons associated with uranium. Due to
- 40 the pyrophoric nature of uranium turnings and chips, internal exposure was related primarily to
- inhalation of uranium. The years of operation and radionuclides are shown in Tables A.3-1 and A.3-2
- 42 respectively in Appendix A.

Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 13 of 38
----------------------------	-----------------	--------------------------------	---------------

### 2.3.1 313 Uranium Metal Fuels Fabrication Facility

1

20

35

2 The aluminum-clad fuel for the first eight production reactors was produced in the 313 Building starting in Mar. 1944 (Key dates doc says Dec. 1943). Natural uranium billets or bars were heated to 3 4 a red heat and shaped into long rods using an extrusion press (see 314 building below). These were 5 cut into shorter lengths called slugs using a turret lathe. After receiving a finish cut in another turret 6 lathe, the slugs were degreased using nitric acid. The cleaned slugs were dipped in a succession of 7 molten baths (i.e. triple-dip method) and pushed into an aluminum can. An aluminum cap was pushed into the can and the top edge of the cap was welded to the can. Bismuth fuel targets were 8 9 fabricated in the 313 Building beginning in 1944. These were irradiated in the production reactors to produce <sup>210</sup>Po (used as an initiator in the earliest atomic weapons). Lead-cadmium fuel rods, welded 10 into non-bonded aluminum cans, were produced for use as "poison" elements for the production 11 reactors. Lithium targets were manufactured for tritium production from 1949 to 1952 and again from 12 1965 to 1967. In the 1950's, production reactor fuel changed from natural uranium to low enriched 13 uranium (LEU). In Mar. 1954 a new, simpler, canning method involving a lead-dip process was 14 15 initiated to replace the old method. All uranium scrap and waste from these processes was salvaged 16 as uranium oxide and shipped off the Hanford site. In 1955 the fuel production facilities were 17 expanded to produce the fuel for the K Reactors. In Jan. 1971 the manufacture of aluminum-clad fuel used in the first six reactors was terminated. After that time, only N-Reactor fuel was manufactured 18 19 (see section 2.3.3 below).

#### 2.3.2 314 Uranium Metal Extrusion Facility

21 The 314 building was known as the Press Building, Metallurgical Engineering Laboratory and later as 22 the Uranium Metal Extrusion Facility. Operation of the 314 Press Building was commenced in July 23 1944 with a mission to process raw uranium billets into extruded rods that were suitable for fabrication 24 into fuel elements. In early 1945, a 1000-ton large extrusion press was installed in the 314 building. 25 After installation, the 313 and 314 buildings assumed all of the fuel manufacturing responsibilities for 26 Hanford. An additional mission, uranium scrap recovery, was started in 1945. An oxide burner was 27 operated outside the building in 1946. A milt plant started operation in December 1947. Uranium 28 scraps were mixed with UF<sub>4</sub> (green salt) and calcium chips. Conversion to metal took place in a 29 reduction furnace (HS300AHD). The high air contamination that occurred frequently, involved a highly soluble, class F material. The milt plant was shut down in 1954. The uranium billets were 30 31 extruded into rods, outgassed and straightened in the 314 building. The extrusion process was 32 terminated in 1948 the fuel element process was changed to use rolled uranium rods. An oxideburner was installed in the 314 building in 1946. In1950, a rolling mill was installed in the 314 building 33 in order to fabricate Hanford fuel elements on site. The building was deactivated in 1971. 34

#### 2.3.3 333 Fuel Cladding Facility

The N Reactor fuel was produced in the 333 building starting in 1961. The N Reactor fuel elements used a tube-in-tube design consisting of slightly enriched uranium inner and outer cores and thin zircaloy-2 cladding. The production process included: cleaning of the uranium billets and Zirconium-2 cladding shells; billet assembly and preheating; extrusion; fuel element shaping and cleaning; and welding of the end cap. In 1965 -1967 outer driver fuel elements were produced in support of tritium production at N Reactor. The Li/Al inner target element was manufactured in the 3722 Area Shop. The 333 building was placed on standby in 1988 when the manufacture of N Reactor fuels ceased.

Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 14 of 38
			1.0.30 0.00

#### 2.3.4 1 306 Reactor Fuel Manufacturing Pilot Plant

- 2 Construction on the 306 building was completed in 1956 and it began operation in May 1957 as a pilot
- plant for reactor fuel production. The 306 building had a complete fuel element canning line with the 3
- 4 exception of autoclaving. The co-extrusion process was developed in the 306-E building in the early
- 1960's in support of the N Reactor fuel needs. This facility was shut down in 1984\*. 5

#### 6 2.3.5 303 Facilities Fresh Metal Storage Facilities

- 7 Ten buildings (303-A, B, C, D, E, F, G, J, K, and M) were built over a period of years from 1944
- 8 to 1983 to store fresh uranium, chemicals, uranium scraps and plutonium. Uranium was shipped to
- 9 Hanford in the form of metal billets. The metal billets were moved to the 303 Fresh Metal Storage
- 10 buildings where they were inspected, entered into accountability records and held for processing. The
- 303-J building was built in 1961 to house a uranium oxide burner and was shutdown in 1971 because 11
- of ventilation problems. In 1983, the new Oxide Burning Facility (303-M) was placed into operation at 12
- the same site. It operated from 1984 to 1987. In 1970\*, the 303-C building was utilized by PNNL for 13
- the storage of plutonium and americium. A pressurization of one of the sealed metal storage cans 14
- 15 resulted in the spread of plutonium contamination and the subsequent shut down of the building until
- 16 cleanup. It currently is being used for other purposes.

#### 2.4 PLUTONIUM FINISHING FACILITIES

17

35

- 18 Two plutonium finishing facilities, 231-Z (Plutonium Isolation Building) and 234-5Z (Plutonium
- 19 Finishing Plant Complex) operated at Hanford from 1945 to present. The latter is still involved in
- 20 plutonium stabilization efforts as a part of the Hanford cleanup program. Both of these complexes are
- located in the 200-W Area. As noted in section 2.4.3 below, the Plutonium Finishing Plant Complex 21
- 22 consists of several buildings including: the 234-5Z that involves several processes (i.e. Rubber Glove
- 23 line, Remote Mechanical A line, Remote Mechanical C line, and RECUPLEX); the 232-Z Incinerator;
- 24 the 236-Z Plutonium Reclamation Facility; and the 242-Z Waste storage Facility. External exposures
- 25 were related to radiation fields primarily from plutonium low-energy x-rays and spontaneous fission
- 26 neutrons. During the early years of plutonium finishing operations, essentially all photon radiation
- resulted from plutonium x-rays. Later, 60 keV gamma radiation from 241Am contributed significantly 27
- 28 to worker exposure. Neutron radiation was substantially elevated in part of the finishing operation
- where alpha radiation from plutonium produced neutrons as a result of the  $\alpha/\eta$  reaction with fluorine. 29
- 30 Although relatively few Hanford personnel were involved in plutonium finishing, these facilities
- 31 provided the majority of personnel exposures to neutron radiation. Internal exposures were related to
- 32 contamination incidents involving americium and plutonium. These exposures occurred by inhalation.
- absorption and injection (i.e. wound sites). The years of operation and the radionuclides of concern 33
- 34 are listed in Tables A.4-1 and A.4-2 respectively in Appendix A.

#### 2.4.1 231-Z Plutonium Isolation Facility

- 36 The 231-Z, Plutonium Isolation Facility began the plutonium finishing process in Jan. 1945 when the
- first plutonium nitrate solution was received. Adding hydrogen peroxide to separate the plutonium 37
- 38 from the nitrate solution purified plutonium. Until July 1949 the plutonium was dried and shipped
- 39 offsite for further refining. When the 234-5Z (see Table A.4-1) went into operation, in July 1949, the
- 40 refined product was shipped offsite for plutonium finishing. Chemical processing was continued in the
- 231-Z building until 1956 when all steps were transferred to the 234-5Z building. In 1956 the 41
- 42 plutonium metallurgy developmental laboratory was moved from 234-5Z to 231-Z. The 231-Z building
- continued to be used for metallurgical research on plutonium and alloys until 19UNK. Studies on the 43
- use of U-233 were also performed in this building. 44

Revision No. 00 Document No. O	RAUT-TKBS-0006-2 Page 15 of 38
--------------------------------	--------------------------------

Table 2.4.1-1. Plutonium nitrate processing tasks.

Task	Name	Function
ı	Purification, Oxalate Precipitation, Wet	Precipitate the plutonium-nitrate feed solution with Oxalic
	Chemistry, or Feed Production	acid and other agents;
П	Hydrofluorination or Dry Chemistry	Diffuse hydrogen fluoride gas through the precipitate;
III	Reduction	Combine the plutonium tetrafluoride with calcium; Fire at
		high temperature until fused into a metallic plutonium
		chunk called a button;
IV	Casting	Render plutonium buttons into pits;
V	Machining	Machine the pit to specified dimensions;
VI	Cleaning	Chemically clean the pit;
VII	Coating	Coat the pit for radiation safety; and
VIII	Final Inspection	Inspect the pit for correct specifications.

# 2

1

### 2.4.2 <u>234-5Z Plutonium Finishing Plant Complex</u>

- 4 The 234-5Z building was used starting in July 1949 for plutonium finishing operations. The Plutonium
- 5 Finishing Plant (PFP) Complex consists of the 234-5Z building including several production areas and
- 6 several other buildings discussed in subsequent sections. The building is currently under going D &
- 7 D.

29

#### 8 2.4.2.1 Rubber Glove Line

- 9 The Rubber Glove (RG) Line in the 234-5Z building was used starting in July 1949 for processing
- 10 plutonium nitrate. All of the tasks listed in the following table with the exception of task 1 were
- 11 performed in the RG line.
- 12 In Dec. 1949, production was temporarily halted to make repairs to solve operational and mechanical
- problems. It was restarted early in 1950. The RG line was placed on standby at the end of Mar. 1953
- with the exception of the coatings units that were shutdown in May 1953. In 1955, equipment from
- 15 Tasks I and II was removed and buried. A majority of the remaining process equipment was removed
- from the RG line in early 1957 in preparation for installation of the new RMC line.

### 17 2.4.2.2 Remote Mechanical A Line

- 18 The Remote Mechanical A Line (RMA) was designed to reduce worker radiation exposure by
- 19 automating the process described in the above table. In Mar. 1952, the RMA line began to process
- 20 the plutonium (IV) oxalate that was prepared in 231-Z. By Mar. 1953 the RMA line began handling all
- of the plutonium work. In July 1954 a fire in the RMA line stopped fabrication of pits for three weeks.
- The RMA line was taken completely out of service in 1964. The weapon fabrication portion of the
- 23 RMA line was removed (see RMC line below) in Mar. 1966. In Sept. 1967, a glove box in the RMA
- line was reactivated in order to grind plutonium-aluminum scraps into turnings suitable for plutonium
- 25 recovery. In 1968, Tasks I-III of the RMA line were cleaned out and reactivated to participate in
- 26 expanded programs for commercial (i.e. non-defense) nuclear development and experiments such as
- 27 oxides for the Hanford Fast Flux Test Facility. In 1984, it was decided to keep the RMA line in
- 28 standby status. It was never operated again.

### 2.4.2.3 Remote Mechanical C Line

- 30 The Remote Mechanical C Line (RMC) began processing plutonium nitrate feed in Oct. 1960. In1962
- 31 a project was undertaken to install ten-inch thick water-filled shielding tanks to substantially reduce

Effective Date: 10/02/2003   Revision No. 00   Document No. ORAUT-TKBS-0006-2   Page 16 of 38
---

- 1 the neutron exposure to operators. Because of fire(s) in other facilities and the RECUPLEX criticality,
- 2 other safety improvements including a new criticality alarm system, a new air sample counter and a
- 3 new paging system were installed in 1963 and 1964. By 1964 the RMC line was being used for a bulk
- 4 of the metal processing and the throughput was increased substantially. As a result of a decision to
- 5 concentrate weapon fabrication work at Rocky Flats, the fabrication portion of the RMC line was
- 6 removed in Mar. 1966. The line continued to operate on a mixed schedule for the next several years
- 7 producing weapons-grade plutonium and fuel-grade plutonium and oxides. As a result of the
- 8 explosion in the americium recovery process in the 242-Z facility, the RMC line was shutdown in
- 9 1976. After preparing to restart production of weapons-grade components, the RMC Line restarted in
- 10 July 1985. The RMC line was permanently shut down in May 1989.

### 11 2.4.2.4 Recovery of Uranium and Plutonium by Extraction Facility

- 12 The Recovery of Uranium and Plutonium by Extraction (RECUPLEX) process facility began in July
- 13 1955, over the next few years; the facility was heavily used with increasing equipment failures and
- increasing radiation levels. In Feb. 1960, RECUPLEX was temporarily shut down to permit an
- extensive cleanup of hoods and operating equipment. In Apr. 1962, a criticality accident resulted in
- 16 widespread contamination throughout the RECUPLEX room and in high external exposures to several
- 17 workers. In May 1962 the Atomic Energy Commission decided to deactivate that section of the 234-
- 18 5Z facility.

### 19 2.4.2.5 232-Z Incinerator Facility

- 20 In Jan. 1962, the 232-Z Incinerator began processing miscellaneous solid wastes to recover small
- 21 quantities of plutonium. The process involved incineration of combustible materials, leaching non-
- 22 combustible materials in nitric acid and wet leaching of ash. The recovered plutonium was transferred
- to RECUPLEX and later the Plutonium Reclamation Facility. In 1973 the 232-Z incinerator was shut
- 24 down.2.4.3.6 236-Z Plutonium Reclamation Facility
- 25 The 236-Z Plutonium Reclamation Facility (PRF) was placed into operation in May 1964 to recover
- 26 plutonium from liquid waste generated in the plutonium finishing plant operations. Using a solution of
- 27 tributyl phosphate diluted with carbon tetrachloride, metal nitrates and other wastes were stripped
- from a plutonium bearing feed. Nitric acid-hydroxylamine solution was then used to separate the
- 29 plutonium as a nitrate. The plutonium nitrate was then ready as a feed for the RMA and RMC lines.
- 30 In Dec. 1975, 236-Z was shut down for maintenance upgrades and reviews of criticality safety
- 31 specifications and procedures. In 1976 the 236-Z operated for only a short time after restart until the
- 32 explosion in 242-Z resulted in widespread, high levels of 241Am contamination in the work area. This
- 33 accident resulted in the shutdown of the entire Plutonium Finishing Complex in April 1976. Any
- internal exposures would be the result of an accident.

### 35 2.4.2.6 236-Z Plutonium Reclamation Facility

- 36 The 236-Z Plutonium Reclamation Facility (PRF) was placed into operation in May 1964 to recover
- 37 plutonium from liquid waste generated in the plutonium finishing plant operations. Using a solution of
- 38 tributyl phosphate diluted with carbon tetrachloride, metal nitrates and other wastes were stripped
- 39 from a plutonium bearing feed. Nitric acid-hydroxylamine solution was then used to separate the
- 40 plutonium as a nitrate. The plutonium nitrate was then ready as a feed for the RMA and RMC lines.
- In Dec. 1975, 236-Z was shut down for maintenance upgrades and reviews of criticality safety
- 42 specifications and procedures. In 1976 the 236-Z operated for only a short time after restart until the
- explosion in 242-Z resulted in widespread, high levels of <sup>241</sup>Am contamination in the work area. This
- 44 accident resulted in the shutdown of the entire Plutonium Finishing Complex in April1976.

Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 17 of 38
			1. 0.30 1. 0.00

### 1 2.4.2.7 242-Z Waste Treatment Facility

- 2 The 242-Z Waste Treatment Facility began operation in 1963 to recover plutonium from aqueous
- 3 waste streams from the PFP. An americium-241 recovery process was installed in a glove box in
- 4 242-Z and began operation in May 1965. The recovery process was converted from a batch to a
- 5 continuous process in 1969. In April 1976, the 242-Z facility was shut down as a result of a strike. In
- 6 August 1976 during restart of the americium recovery process, an explosion occurred in a cation ion
- 7 exchange column containing approximately 100 grams of americium-241. This resulted in substantial
- 8 Americium internal exposure. As a result, the 242-Z facility was permanently closed. Doors into the
- 9 operating area were welded shut and the facility currently is waiting D&D efforts.

### 10 2.4.3 Plutonium Storage Facilities

- 11 Several plutonium storage facilities were constructed at the PFP (234-5Z) starting in 1949. These
- 12 include: 2736-Z, 2736-ZA, and 2736-ZB built in 1971, 1977, and 1982 respectively. There were 12
- vault or vault-type rooms in the PFP. These vaults contained 93 percent of the Hanford Site's
- unirradiated plutonium items and 92 percent of the total Hanford unirradiated plutonium inventory in
- 15 July 1994 at the time the Plutonium Vulnerability Study (DOE, 1994) was performed. External
- 16 exposure in the vault rooms from low-energy photons and neutrons occurred during periodic inventory
- 17 and inspection activities. Internal exposure was minimal since there were no routine activities that
- involved opening the storage containers. Internal exposure would have been a concern in the event
- of an incident that voided the containment afforded by the storage containers. Stabilization efforts
- were completed in Aug. 2003.

### 21 2.5 RESEARCH, DEVELOPMENT, AND TESTING FACILITIES

- 22 The 21-major Research, Development, and Testing Facilities at Hanford were located in the 100, 200
- and 300 Areas. Construction of these started in 1944 with the last one completed in 1977. These
- 24 facilities were built to support the development and testing of new processes, materials, and
- 25 equipment. In some instances the facilities were used for several different purposes throughout their
- 26 operating life. Therefore, the potential exposures are dependent on the processes involved and the
- 27 mission/process at any given time. The years of operation and the radionuclides of concern are listed
- 28 in Tables A.5-1, A.5-2 and A.5-3 in Appendix A.

### 29 **2.5.1 108-F Biology Facility**

- 30 The 108-F building was remodeled in 1949 to provide laboratory and office space for the Hanford Site
- 31 Biology Program. The facility was used to perform radiation effects studies on plants, animals and
- 32 fish in support of Hanford plant operations. Studies involved many radionuclides including 90Sr, 131I,
- 33 <sup>238</sup>U, and <sup>239</sup>Pu. The building was expanded in 1953 and again in 1962 to provide additional space for
- 34 biological experiments. The facility was closed in 1977 when the Biology Program moved to the 331
- 35 building (see section 2.5.16 below).

### 36 2.5.2 <u>120 Critical Mass Laboratory Facility</u>

- 37 The Critical Mass Laboratory was originally operated in the 120 building located near the 100-F Area
- 38 starting in Apr. 1950. This laboratory was used for nuclear physics R&D studies of plutonium
- 39 solutions and solids to avoid the accidental occurrence of a criticality event in an operating facility. In
- 40 Nov. 1951, a substantial spread of contamination occurred as a result of an experiment performed
- 41 with a plutonium solution. In Dec. 1950, spontaneous ignition of rags soaked with nitric acid occurred
- 42 during cleanup. While the metal building was not destroyed, the facility was permanently closed due

Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 18 of 38
			1. 0.30 .0 0. 00

- 1 to the extensive plutonium contamination. The site was subsequently decontaminated and
- 2 decommissioned.

### 3 2.5.3 <u>209-E Critical Mass Laboratory</u>

- 4 The 209-E Critical Mass Laboratory was placed into operation in July 1961. The laboratory, located in
- a room shielded by at least 3 ft of concrete, included a mixing room with a glove box and mixing hood
- 6 and a control room from which critical mass physics experiments were remotely conducted. Both
- 7 <sup>239</sup>Pu and <sup>240</sup>Pu was used in the criticality studies. As a result external exposures were minimized.
- 8 Internal exposures were related to contamination incidents involving plutonium. This facility was shut
- 9 down in 1986\* after a series of occurrences involving criticality safety specifications.

### 10 **2.5.4 222-B Laboratory**

- 11 The 222-B laboratory was opened in the 222-B building in 1945 to perform process or research and
- development radiochemical operations in support of irradiated fuel-reprocessing facilities. One of the
- main functions was to test the solution samples from the 221-B and 224-B buildings at various steps
- in the separations process. External and internal exposures were associated with the FP and
- 15 plutonium in the process samples. It was shutdown in ~1975. This facility was converted to office
- 16 space.

### 17 **2.5.5 222-S Laboratory**

- 18 Construction of the 222-S laboratory was started in 1949. The laboratory contains laboratories and
- 19 shielded cells that were used to provide analytical services in support of process control of REDOX,
- 20 B-Plant and 242-S and 242-A Evaporators. It currently is used for analytical operations in support of
- 21 waste management and environmental control processes. External exposures were related primarily
- to FP in process samples. Internal exposures would primarily be associated with samples associated
- with the separations plants process samples (e.g. FP and plutonium). In the early 1960's, some work
- was performed with <sup>147</sup>Pm. Internal exposures were primarily related to contamination incidents.

#### 25 **2.5.6 222-T Laboratory**

- 26 The 222-T Laboratory was the first to operate commencing in 1944 in support of the separation
- 27 process in 221-T and supporting work in 224-T. External and internal exposure potential was similar
- to that in 222-B above. It was shutdown in 1980\*. Fire protection was shutoff in 1986.

#### 29 2.5.7 308 Plutonium Fuels Pilot Plant

- 30 The Plutonium Fuels Pilot Plant (PFPP) was constructed in the 308 building in1960 to perform
- 31 research and development on fuel elements used in the PRTR. In the mid 1960's the PRTR fuel work
- was terminated. In the late 60's, neptunium-aluminum alloy fuel target elements were produced for
- use in N Reactor for a Pu-238 production run. A high bay area was added to the building in 1971. A
- 34 <sup>147</sup>Pm contamination incident occurred in the 308 building in 1971. From 1977 to 1991 the facility was
- 35 used for the production of FFTF fuel elements. The 308-A annex was added to the Plutonium
- 36 Fabrication Pilot Plant in 1979 to accommodate additional plutonium fuels work. A 250 kW Training
- 37 Research Isotopes, General Atomics (TRIGA) reactor was installed in the annex in the late 1970's to
- perform neutron radiography, a feature of the QA testing program. During its operation, the building
- 39 experienced many incidents involving the loss of control of radioactive materials, primarily plutonium.
- 40 Most of these were contained within usually one laboratory and in adjacent corridors. Glove box fires,
- 41 explosions, and/or ruptures were the most frequent cause of contamination. Improperly sealed

Effective Date: 10/02/2003 Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 19 of 38
--	--------------------------------	---------------

- irradiated sample containers were another common cause. These incidents occasionally resulted in 1
- 2 internal exposures. The 308 facilities were deactivated in 1990\*.

#### 3 2.5.8 318 Radiological Calibration and Development Laboratory

- The 318 building was originally built in 1967 to house the HTLTR reactor (see section 2.1.8). In the 4
- early 1980's, the reactor was removed and the heavily shielded10-meter cube reactor cell was 5
- converted to a free-in-air calibration facility that contains a large <sup>252</sup>Cf neutron source (10<sup>9</sup> n/s) and a 6
- large <sup>137</sup>Cs photon source (~100 Ci) that were used for dosimeter calibration. A shielded facility was 7
- built in the basement to house a high-level <sup>60</sup>Co source (~1kCi) to create accident dose rate levels 8
- and three 300 kVp X-ray machines. The calibration laboratory commenced operation in 1983. Three 9
- major additions were constructed in 1985, 1987 and 1989. The first contained four source wells that 10
- held two <sup>137</sup>Cs, one <sup>60</sup>Co, and one <sup>252</sup>Cf sources used for instrument calibration. The second addition 11
- 12 houses instrument testing and repair laboratories and the last addition provided office facilities for the
- 13 staff. As a result of the shielding, isolation, remote operations, and operating procedures, external
- 14 exposures were minimized. Internal exposures were negligible. The facility is still in operation.

#### 2.5.9 320 Low-Level Radiochemistry Facility 15

- 16 The Low-Level Radiochemistry Laboratory was built in the 320 building in 1966. The original mission
- 17 was to house analytical chemistry services and provide plant support involving low-level and non-
- 18 radioactive samples. The 320 Building currently provides a low-level radiochemistry facility in which
- very sensitive radiochemical analysis, sample preparation, and methods development can be 19
- 20 performed. External and Internal exposures were minimal. The facility is still in operation.

#### 21 2.5.10 321 Separation Facility

35

- 22 The 321 Separation Facility (Cold Semi-Works) was built in 1944 with a mission to be used as a cold
- 23 (i.e. non-irradiated material) pilot plant to test the bismuth phosphate chemical reprocessing methods
- 24 and equipment and to study problems as the 221, 224, and 231 buildings were being constructed. In
- 25 late 1944, it was decided to add a laboratory for work with small amounts of solutions containing
- several tenths of a curie to a curie of radioactive materials (Gerber, 1993; HS300AHD). Soon after 26
- 27 start-up, the 321 building assumed a mission to demonstrate the effects of proposed process changes
- 28 on decontamination factors in the 221, 224, and 231 buildings, conducting isotope separations, and
- 29 experiments on small-irradiated samples. In 1949 321 was used to develop the REDOX process.
- 30 Tests using radioactive materials were discontinued after 1949. The 321 building was used in 1953 to
- 31 perform a cold test of the PUREX process. Pilot scale tests of the U-Plant recovery process were
- conducted in 1955. Isotope Campaigns were conducted in the 1960's using tracer-levels of 32
- <sup>90</sup>Sr, <sup>137</sup>Cs, <sup>144</sup>Ce, <sup>147</sup>Pm, and <sup>237</sup>Np. Primary contamination in the facility was due to thorium and 33
- uranium. External and Internal exposures were minimal. The building was deactivated in 1988. 34

#### 2.5.11 324 Chemical and Materials Engineering Laboratory

- The Chemical and Materials Engineering Laboratory began operation in 1966 to provide research and 36
- 37 development studies in support of the PRTR operations. It was used first as a fuel recycle pilot plant
- 38 by housing chemical reprocessing and metallurgical examination capabilities used for PRTR fuel
- elements. It consisted of two groups of large shielded cells used for both radiochemical and 39
- 40 metallurgical studies. The chemistry cells consisted of four cells connected to an air lock where
- 41 studies of various processes for solidifying high-level liquid waste were performed. It was used in
- 42 conjunction with the 325-A hot cells to perform studies on solidification of high-level liquid waste (i.e.
- 43 Nuclear Waste Vitrification Project) from processing irradiated fuel elements from commercial

Effective Date: 10/02/2003   Revision No. 00   Document No. 0	ORAUT-TKBS-0006-2	Page 20 of 38
---	-------------------	---------------

- 1 reactors). A special underground liquid waste pipe line connected the hot cells in 324 and 325-A.
- 2 Most recently, it was used as a Waste Technology-Engineering Laboratory. Since most of the work
- 3 was performed in hot cells, external and internal exposures were minimized. The 324 building is
- currently undergoing decontamination and decommissioning activities. 4

#### 5 2.5.12 325 Radiochemistry Laboratory

- 6 The 325 building was completed in 1953 to permit multi-curie level chemical development work in
- 7 support of production and process improvement (Marceau, 2002; HS300AHD). A high-level
- 8 radiochemistry wing, 325-A, was placed into operation on the east side of the building in 1959/1960.
- It included three large hot cells for isotope research activities. This included separation and 9
- concentration of <sup>90</sup>Sr, <sup>90</sup>Y, <sup>131</sup>I, <sup>137</sup>Cs, <sup>144</sup>Ce<sup>147</sup>Pm, <sup>210</sup>Po, <sup>238</sup>Pu, <sup>239</sup>Pu, and <sup>244</sup>Cm for special programs. The <sup>147</sup>Pm was used in the manufacture of heat sources starting in 1966. The <sup>210</sup>Po work started in 10
- 11
- June 1972 and was terminated in 1970\*. In 1990\*, 90Y was separated from 90Sr in multi-Curie 12
- quantities for medical use. These cells were also used in support of the studies on solidification of 13
- high-level radioactive waste (i.e. Nuclear Waste Vitrification Project) from processing irradiated fuel 14
- 15 elements from commercial reactors. A special underground liquid waste pipe line connected the hot
- 16 cells in 324 and 325-A. The Nuclear Waste Vitrification Project that was conducted in the 324 and
- 17 325 buildings in the 1970's, involved high "burnup" commercial fuel elements were characterized by
- nominally 26% <sup>240</sup>Pu (Carbaugh 2003). High-level radio-analytical hot cells were added on the west 18
- side in 19UNK. The building became known as the Radiochemistry/Cerium recovery Building. 19
- 20 Limiting access to high-level dose-rate or contamination areas controlled external and internal
- 21 exposures. Most exposures were related to maintenance performed in hot cells or accidents in
- 22 laboratory areas where work was being performed with FP, plutonium, and other radionuclides. A
- 23 major <sup>147</sup>Pm contamination incident occurred in the late 1960's. The radiochemical laboratory work
- resulted in external exposure and any internal exposure resulted from contamination incidents. The 24
- 25 325 building still is in use in support of cleanup efforts at Hanford.

#### 2.5.13 326 Pile Physics Technology and Metallurgy Facility 26

- Operation of the 326 building started in 1953 to continue exponential pile physics development work 27
- 28 originally performed in the P-11 Facility and later in 189-D (Marceau, 2002; HS300AHD). Po-Be and
- 29 Ra-Be neutron sources with neutron emissions up to 1X10E+8 n/s were used to irradiate Co and Cu
- 30 test foils. The test foils exhibited radiation levels up to 10 rad/h at 3 inches. The facility was also
- 31 used for metallurgical studies of reactor components and fuel elements to evaluate characteristics and
- 32 performance. Some of this work was transferred to 209 E in 1961. A High Energy Electron
- 33 Microscope was installed in the basement in 1971 to perform materials studies. During microscope
- 34 operations, there was a major spread of plutonium and irradiated steel (i.e. Fe) contamination. This
- 35 and other contamination incidents resulted in some internal exposure. In 1983 the 326 building
- 36 became the "Chemical Science Building". This facility is still in operation.

#### 37 2.5.14 327 Radiometallurgy Laboratory Facility

- 38 The 327 Radiometallurgy Laboratory was built in 1953(?) to replace the 111-B Test Building (Gerber,
- 39 1993; Marceau, 2002; HS300AHD). It was designed to provide for post testing and other studies on
- 40 irradiated materials, particularly fuel elements and fuel cladding materials from and for the production
- 41 reactors. These facilities originally consisted of eight free standing shielded cells and two water-filled
- 42 storage pools. Several modifications were undertaken to provide a shielded load out facility to handle
- 43 high-level radioactive waste, a large shielded cell to perform special environmental Radiometallurgy
- 44 studies and office space. In 1967 it was used for the experimental production of Pu-238. It was used
- to study irradiated PRTR, FFTF, GETR, EBR II and MTR fuel elements. In 1967 it was involved in a 45

Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 21 of 38
	1 (0 ) (0 ) (1 ) (0 )	Boodinon No. O. W.O. TREE COOL E	1 ago = 1 o. oo

- 1 serious contamination event. The 327 building was renamed the Post Irradiation Testing Laboratory
- 2 in the 1980's. External and internal exposures were related to irradiated materials, and FP that were
- undergoing metallurgical studies. Work was also performed with <sup>233</sup>U and <sup>238</sup>Pu. The facility was 3
- 4 deactivated in 1987.

#### 5 2.5.15 329 Biophysics Laboratory

- 6 The biophysics laboratory was opened in 1952 to pioneer development of water chemistry,
- 7 environmental monitoring, and bioassay analysis programs. Missions for the Laboratory include the
- 8 analyses of low-level (i.e. near background) quantities of radioactive materials in air, vegetation, soil,
- wildlife, river and well water samples. A neutron multiplier facility was built in 1974 as section D of the 9
- biophysics laboratory. It commenced operation in 1977 with a large <sup>252</sup>Cf source. External and 10
- 11 internal exposures were minimized. The building is still in operation.

#### 12 2.5.16 331 Life Sciences Laboratory Facility

- The Life Sciences Laboratory opened in the 331 building in 1972 as a replacement to the 108-F 13
- complex. The facility was used to perform radiation effects studies on plants, animals and fish in 14
- support of Hanford plant operations. Studies involved many radionuclides including 90Sr. 131I. 238U. 15
- and <sup>239</sup>Pu. A hot cell that originally contained a 15 kCi <sup>60</sup>Co source was used for special irradiation 16
- studies. External and internal exposures were a minimum. The facility is still in operation. 17

#### 18 2.5.17 3706 Radiochemistry Laboratory

- 19 The 3706 building, the original radiochemistry laboratory was placed in operation in early1945
- 20 (Gerber, 1993; Marceau, 2002; HS300AHD). This building was also known as the Technical Building.
- The original mission was to perform small-scale experiments with both low- and high-activity 21
- 22 radioactive materials in support of production activities with the primary focus on improving the
- 23 bismuth phosphate process. The QA/QC activities associated with fuel element fabrication also were
- 24 performed in 3706 building. Another mission was the metallurgical examination of irradiated fuel
- 25 elements, fuel development for the 313 Building, examination of graphite from the experimental levels
- of the 100 Area piles and special sample analyses from 231Z and 200 Area separation facilities. In 26
- 27 1947, it was used in the development of the REDOX process. Pioneering radiochemistry work in the
- 28 development of the REDOX, PUREX, and RECUPLEX processes was performed until 1953. Work
- 29
- involved many radionuclides including FP, <sup>14</sup>C, <sup>131</sup>I, <sup>235</sup>U, <sup>238</sup>U, and <sup>239</sup>Pu. External and internal exposures were related to these radionuclides. Thyroid checks were initiated in May 1947. In 1954, 30
- many of the laboratories were decontaminated and converted to offices. During the 1970's and 31
- 1980's most of the remaining building was converted to offices and still were in use in the early 32
- 33 1990's.

#### 34 2.5.18 3730 Gamma Irradiation Facility

- 35 The 3730 building was originally constructed in 1949 as a shop. In 1956 the work performed in the
- 3741 building was transferred to this building. A 350 kCi Co-60 source was added to a pool in the 36
- 1960's for special irradiation studies. Irradiated samples measured from 25 to 50 rad/h. Respiratory 37
- protection was required in the 1950's because of <sup>14</sup>C and <sup>35</sup>S airborne contamination. Several facility 38
- 39 improvements were made during 1974 to 1981.

Ellective Date: 10/02/2003   Revision No. 00     Document No. ORAOT-TRD5-0006-2   Page 22 01 36	1	Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 22 of 38
---	---	----------------------------	-----------------	--------------------------------	---------------

#### 1 2.5.19 3732 Process Equipment Development Laboratory

- 2 The 3732 Process Equipment Development Laboratory was constructed in 1949 as an engineering
- pilot plant for the triple-dip and lead-dip fuel canning processes (WHC-MR-0388). It is a one-story, 3
- 4 metal frame structure seated on a concrete foundation, with a concrete floor and a corrugated metal
- 5 roof. Overall dimensions are 28.5 ft by 48.16 ft. Powdered thorium oxide fuel targets for <sup>233</sup>U
- 6 production were fabricated in the 3732 Building from 1965 to 1967. The process of handling these
- 7 powder targets spread powdered and particulate thorium contamination throughout the building. After
- the thorium oxide program switched to pelletized targets in the 3722 Building in 1968, these new fuel 8
- 9 targets were canned in the 3732 Building through 1970. As a result, the 3732 building contains
- standard fuel fabrication chemical wastes, as well as residual thorium oxide contamination in crevices 10
- and areas throughout and near the building. The facility is now empty. 11

#### 12 2.5.20 **3741 Graphite Hot Shop Facility**

- 13 The Graphite Hot Shop was constructed in 1944 to perform metallurgical studies on irradiated
- 14 graphite samples. Po-Be and Ra-Be neutron sources were used in irradiation facilities in the
- 15 basement to irradiate Co and Cu foils Internal exposures would have been primarily due to the large
- quantities of irradiated graphite (i.e. <sup>14</sup>C) that were studied. The facility was torn down in 1956 and 16
- work was transferred to 3730 (HS300AHD). 17

#### 18 2.5.21 3745 Radiological Calibrations and Standards Laboratory

- 19 The Radiological Calibrations and Standards Laboratory was opened in the 3745 building in Oct.
- 20 1944. The two-story wooden frame building contained a low scatter room in which dosimeters were
- calibrated using a <sup>226</sup>Ra source and a 220 kVp X-ray machine. Other sources used included large <sup>60</sup>Co and <sup>137</sup>Cs photon sources and <sup>252</sup>Cf, <sup>226</sup>Ra-Be, <sup>84</sup>Po-B, <sup>84</sup>Po-Be, <sup>238</sup>Pu-Be, <sup>239</sup>Pu-F, and <sup>124</sup>Sb-Be 21
- 22
- neutron sources. Instrument calibrations were performed in a different room that contained two 23
- 24 vertical concrete-shielded wells in which the photon sources were housed and used. Instrument
- calibration sources included <sup>60</sup>Co, <sup>137</sup>Cs, and <sup>1226</sup>Ra sources. A supporting facility, 3745B, was 25
- 26 constructed out of concrete blocks to house a 4 MeV Van de Graff positive ion accelerator. This was
- 27 used starting in 1955 to perform fast neutron calibrations. A companion facility, 3745A, was built in
- 1950\* to house a 2 MeV negative ion Van de Graff accelerator. As a result of the shielding, isolation. 28
- 29 remote operations, and operating procedures, external exposures were minimized. Internal
- 30 exposures were negligible. The calibration operations were moved to the 318 building in 1983. The
- 31 building is still used for office space.

33

#### 32 2.6 **WASTE HANDLING FACILITIES**

#### 2.6.1 **High-Level Liquid Waste Tanks**

- High-level radioactive liquid wastes from reprocessing facilities at Hanford were stored in underground 34
- 35 single-shell and double-shell tanks starting in 1944. The high-level radioactive waste is transported
- through underground process lines to the storage tanks that are located in tank farms in both 200-E 36
- 37 and 200-W Areas. The storage tanks are of two types, single-shell and double-shell tanks. Both
- 38 types are cylindrical shaped concrete structures with carbon steel liners. The single-shell tank has a
- 39 single liner and the double-shell tank has two liners with a space in between. Initially, the T and B
- 40 Plants produced over 10,000 gallons of high-level radioactive waste for each ton of uranium
- 41 processed. These wastes were transferred to the first 64 tanks constructed in 1944-1945. Thirty new
- 42 single-shall tanks were constructed in 1947-1948. Additional single-shell tanks were constructed in
- 43 1950-1952 (30), in 1953-1955 (21), and 1963-1964 (4). From 1968-1988 a total of 28 double-shell

Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 23 of 38

- 1 tanks was constructed. Most of the single and double shell tanks are still in use. A new waste
- 2 glassification facility is under construction to process the stored high-level liquid wastes. External
- 3 exposure is due to high-energy beta and photon radiations from the fission products stored in the
- 4 tanks. Under normal conditions shielding, distance and time, minimizes personnel exposures. Most
- external exposures would be related to leaks of high-level wastes. Internal exposures to FP were 5
- controlled through the use of respiratory protection. 6

#### 2.6.2 216-Z-9 Trench Facility

7

- 8 The 216-Z-9 Facility known as the (Z-9) crib (i.e. enclosed trench) is located in the 200-W Area
- approximately 500 feet east of the Z Plant (i.e. PFP) exclusion area. The Z-9 trench was placed into 9
- 10 operation in 1955 to serve the RECUPLEX Facility by receiving the acid waste stream of both
- 11 aqueous and organic wastes as well as unwashed fabrication oil from the RMA line from 1955-1962.
- 12 The trench was an underground excavation within an active floor area of 30 by 60 feet, 21 feet
- beneath the top of the concrete slab cover. The excavation was covered by a 9 to 12-inch thick 13
- reinforced concrete slab, 90 feet wide and 120 feet long at ground level. In 1965 because of concern 14
- that the waste plutonium posed a "potential criticality hazard" a decision was made to develop a soil 15
- 16 mining and leaching operation to recover an estimated 45 kilograms of waste plutonium. A~1000 17 square foot containment structure was built underground to conduct the operation. It housed a soil
- 18 packaging glove box, personnel entry to the trench, and a personnel change room. The structure was
- 19 located on the east side of the trench with part of the structure located over the top of the trench
- cover. The mining operator's cubicle, which contained the controls for operating the mining 20
- 21 equipment, was located within the west side of the trench cover through a reinforced opening in the
- 22 trench cover. The mining operation commenced in Aug. 1976 and was completed in July 1978. The
- principal internal exposure potential was related to <sup>239</sup>Pu contamination, most of which occurred in the 23
- soil packaging glove box. Since the waste site was used only for plutonium, the external exposure 24
- potential during the mining operation was minimal. The facility currently is in a laid away status. 25

#### 26 2.6.3 241-Z Settling Tank

- The 241-Z Settling Tank, located within the fence of the PFP complex in the 200 West Area, was used 27
- 28 from 1949-1973 to store large quantities of plutonium-bearing wastes. In 1974, 80,000 liters of
- 29 supernate were removed from the tank leaving an estimated 94-inch deep layer of wet sludge
- containing a few tens of kilograms of plutonium. Internal and external exposures from this operation 30
- 31 are minimal. The facility is currently awaiting D & D efforts.

#### 32 2.6.4 242 Evaporator Facilities

- 33 The evaporator facilities (242-A, 242-B, 242-S and 242-T) were constructed near each of the
- 34 separation facilities to reduce and concentrate the volume of high level wastes. The 242-T and 242-B
- 35 Evaporators started processing high-level radioactive waste starting in 1951. Two new evaporator
- 36 plants, 242-S and 242-A, commenced operation in 1973 and 1976, respectively. External exposure
- 37 would be due to high-energy beta and photon radiations from the fission products stored in the tanks.
- 38 Personnel exposures normally are controlled using shielding, distance and time. Most external
- 39 exposures would be related to leaks of high-level wastes. Internal exposures to FP were controlled
- 40 through the use of respiratory protection. The first three evaporator facilities were shut down in
- 41 19UNK. The 242-A is still in operation.

Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 24 of 38	

### 1 2.6.5 <u>Chemical Separations Exhaust Filtration Facilities</u>

2 Gaseous waste is grouped into three headings: dissolver off-gases, process vessel vent systems, and

exhaust ventilation air. Dissolver off-gases contained the major portion of the radioactive iodine

4 (primarily <sup>131</sup>I), as well as krypton and xenon isotopes. Dissolver off-gases also carried a high

5 concentration of nitrogen oxides resulting from the reduction of nitric acid during the dissolution of the

6 irradiated fuel elements. Table 2.6.5-1 shows the three exhaust filtration devices that were used

7 starting in 1947 to reduce radioactive material releases from the B and T Separations Plants and later

8 the REDOX Plant:

3

9

21

22

26

Table 2.6.5-1. Exhaust filtration facilities.

Filtration Devices	Date Installed			
Caustic scrubbers	1947-1948			
Sand filters and fiberglass filters	1947-1948 1954(REDOX)			
Silver reactors	1950			

10 These filtration devices accumulated substantive quantities of radioactive materials from the

11 separations and plutonium concentrations. The caustic scrubbers were used to remove radio-

12 chemical vapors from the process vessels. Sand filters were installed in the 202-S, 221-B, 221-T,

13 291-B, 291-S, 291-T, 291-Z facilities. The filters were used in exhaust streams associated with the

separations process to remove particulates and to reduce ruthenium emissions from the exhaust

15 stream. Silver reactors were installed primarily to remove <sup>131</sup>I from the exhaust stream.

Radionuclides of interest in the filtration devices include FP, <sup>103</sup>Ru, <sup>106</sup>Ru, <sup>131</sup>I, and <sup>239</sup>Pu. Internal and

17 external exposures associated with these radionuclides would occur primarily during maintenance

operations. These filtration devices became inactive as the separations facilities were shut down.

#### 19 2.6.6 340, 340-A and 340-B Liquid Waste Handling Buildings

20 The 340-facility complex was operated starting in 1954 to receive radioactive liquid wastes from

various 300 Area laboratories via the radioactive liquid waste sewer line. The complex accumulates

the liquid wastes in storage tanks. After sample analyses and pH adjustment, the liquid wastes are

23 shipped via a shielded railcar tank to the 200-E Area Tank Farms for treatment and disposal. The

radionuclides of concern include: <sup>60</sup>Co. <sup>90</sup>Sr, <sup>90</sup>Y, <sup>137</sup>Cs, <sup>147</sup>Pm, <sup>238</sup>Pu, <sup>239</sup>Pu, and <sup>144</sup>Ce. Access to the

25 tank area was administratively controlled. The external exposures to the operators were related to the

high-energy betas and photons. Internal exposures were unplanned and would be related to leaks or

27 an accident. The facility is still in use.

**REFERENCES** 

- Ballinger, M.Y. and R.B. Hall. 1991, A History of Major Hanford Facilities and Processes Involving 2 Radioactive Material, PNL-6964 HEDR, March 3
- 4 Bihl, D. E., R.L. Buschbom, and M.J. Sula, 1993, Experience with a Routine Fecal Sampling Program for Plutonium Workers, Health Physics, 65(5) 5
- 6 Boomer, K.D., et al. 1994, Tank Waste Remediation System Facility Configuration Study, WHC-SD-7 WM-ES-295, June
- 8 Carbaugh, E.H. 2003, Methods and Models of the Hanford Internal Dosimetry Program, PNL-MA-NOTE: Need title, author and date 9 86024) WHC-MR-0388
- 10 Carlisle, R.P., 1996, Supplying The Nuclear Arsenal American Production Reactors, 1942 – 1992, 11 John Hopkins University Press
- 12 Cooke, N., F.B. Holt. 1974. "The Solubility of Some Uranium Compounds in Simulated Lung Fluid." 13 Health Physics, Vol. 27 (July).
- 14 Crowe, R.D. and R.W. Szempruch, 1994, Technical Basis for Characterization of Plutonium for PFP 15 Safety Analyses, WHC-SD-CP-TI-190, February
- 16 Department of Energy (DOE), 1994, Plutonium ES&H Vulnerability Assessment, July 27
- 17 Fisher, D.R. 1986. Letter to Monte J. Sula, "Particle Size Distribution and Solubility of Uranium 18 Aerosols in 333 and 303 M Buildings at UNC and PNL's 306W Building."
- 19 Hanford Site Historical District – Hanford Site 300 Area Historical Directory (HS300AHD)
- 20 Lyon, M.M., et al, 1989, Hanford Radiological Protection Support Services at Hanford for 1988, PNL-21 6952
- 22 Lyon, M.M., J.J. Fix, J.L. Kenoyer, J.A. Leonowich, H.E. Palmer, and M.J. Sula, 1988, Hanford 23 Radiological Protection Support Services Annual Report for 1987, PNL-6624,
- 24 Marceau, T.E., et al. 2002, History of the Plutonium Production Facilities at the Hanford Site Historic 25 District, 1943-1990, DOE/RL-97-1047, June
- 26 McConnon, D. 1966, Exposure Estimates vs. Film Badge Results, Letter to K.R. Heid, April 22
- Newman, D.F., 1989, Summary of HTLTR Benchmark Data from the High Temperature Lattice Test 27 28 Reactor, PNL-7178, October
- 29 Rich, B.L., S.L. Hinnefeld, C.R. Lagerquist, W.G. Mansfield, L.H. Munson, E.R. Wagner, 1988. Health 30 Physics Manual of Good Practices for Uranium Facilities. EGG-2530
- Selby, J.M. and J.K. Soldat. 1958, Summary of Environmental Contamination Releases at Hanford 31 32 1952 – 1957, HW 54636, January 25
- 33 Sula, M.J., E.H. Carbaugh, and D.E. Bihl. 1989, Technical Basis for Internal Dosimetry at Hanford, 34 PNL-6866, April

	Effective Date: 10/02/2003 Revision No. 00 Document No. ORAUT-TKBS-0006-2 Page 26 of 38
1 2	Sula, M.J., E.H. Carbaugh, D.E. Bihl. 1991. Technical Basis for Internal Dosimetry at Hanford. PNL-6866, Rev. 1. Pacific Northwest Laboratory, Richland, WA.
3	Thompson, R.J. 1986, Operating Specifications for the Uranium Oxide Plant, OSD-U-185-00001
4 5 6 7	Till, J.E., P.G. Voilleque, G.G. Killough, and S.K. Rope. 2002, Methods for Estimating Radiation Doses from Short-Lived Gaseous Radionuclides and Radioactive Particles Released to the Atmosphere During Early Hanford Operations, RAC Report No. 2-CDC-Task Order 3-2000-Final,
8 9	Wilson, R.H., 1987, Historical Review of Personnel Dosimetry Development and its Use in Radiation Protection Programs at Hanford 1944 to the 1980s, PNL-6125, February
10 11	Wilson, R.H., W.V. Baumgartner, J.J. Fix, and L.L. Nichols. 1990, Description and Evaluation of the Hanford Personnel Dosimeter Program From 1944 Through 1989, PNL-7447
12 13	Gerber, M.S., 1992, Past Practices Technical Characterization Study – 300 Area – Hanford Site, WHC-MR-0388, December
14	Gerber, M.S., 1993, Manhattan Project Buildings and Facilities at the Hanford Site: A Construction
15	History, WHC-MR-0425, September, UNK
16	19UNK, A Brief History of the T-Plant Facility, WHC-MR-0452, UNK
17	19UNK, The Hanford Site—An Anthology of Early Histories, WHC-MR-0435,
18	19UNK, Plutonium Production Story at the Hanford Site, WHC-MR-0521,
19	19UNK, Brief History of the Purex and UO <sub>3</sub> Facilities, WHC-MR-0437

1	GLOSSARY
2 3	Burnup Depletion of fissionable material i.e., 235Pu
4 5	<b>Mint</b> Tritium
6 7	Pile Reactor

Document No. ORAUT-TKBS-0006-2

Page 27 of 38

Effective Date: 10/02/2003 Revision No. 00

A machined part of a nuclear weapon

**Slugs**Another name for fuel elements

Pit

8

9

10 11

### ATTACHMENT A - DESCRIPTION OF FACILITIES AND PROCESSES

2		TABLE OF CONTENTS	
3	Sectio	<u>n</u>	Page
4	A.1	Reactors	29
5	A.2	Fuel Reprocessing Facilities	30
6	A.3	Fuel Fabrication Facilities	33
7	A.4	Plutonium Finishing Facilities	35
8	A.5	Research and Development Facilities	36
9	A.6	Waste Facilities	37
10		LIST OF TABLES	
11	<u>Table</u>		<u>Page</u>
12	A.1-1	Production reactors years of operation	
13	A.1-2	Radionuclides of concern for all production reactors	
14	A.1-3	Research and test reactors years of operation	
15	A.1-4	Radionuclides of concern for all research and test reactors	
16	A.2-1	Fuel reprocessing facilities years of operation	
17	A.2-2	Radionuclides of concern for all reprocessing facilities	
18	A.2-3	Activity composition of Hanford reference weapons-grade plutonium mixture	32
19	A.2-4	Activity composition of Hanford reference fuel-grade plutonium mixture	32
20	A.2-5	Activity composition of Hanford reference commercial power fuel-grade plutonium	20
21 22	A.3-1	mixture Fuel fabrication facilities years of operation	
22 23	A.3-1 A.3-2	Radionuclides of concern for all fuel fabrication and storage facilities	
23 24	A.3-2	Radiological characteristics of Hanford uranium mixtures	
2 <del>5</del>	A.3-4	Impurities in recycled uranium at Hanford	
26	A.3-5	Inhalation class for Hanford uranium compounds	
27	A.4-1	Plutonium finishing facilities years of operation	
 28	A.4-2	Radionuclides of concern for plutonium finishing facilities	36
29	A.5-1	100 and 200 Area research and development facilities years of operation	36
30	A.5-2	300 Area research and development facilities years of operation	36
31	A.5-3	300 Area research and development facilities years of operation (continued)	
32 33	A.5-4	Radionuclides of concern for all 100, 200, and 300 Area research and development facilities	
34	A.6-1	Waste facilities years of operation	38
35	A.6-2	Radionuclides of concern for all waste facilities	
36	A 6-3	Tank waste radionuclide inventory	38

Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 29 of 38
----------------------------	-----------------	--------------------------------	---------------

#### A.1 REACTORS

1

3

7

9

11

12

14

17

19

23

27

28

29

2 External exposures at the Production Reactors are primarily due to presence of activation and fission

products. During operation, entry was restricted or prevented into areas where high direct dose rates

4 from photons and neutrons could occur.

5 Internal exposures at the Production Reactors are related primarily to the inhalation or absorption of

6 activation products and, to a lesser degree, fission products during refueling and maintenance

operations. Studies in later years at N-Reactor to characterize worker exposure indicated the primary

8 internal exposure in the Production Reactors was due to <sup>60</sup>Co, a corrosion product. It was stated

(Sula, et al 1989), "In general, a major characteristic of these corrosion product radionuclides,

10 regardless of origin, is the presence of several radionuclides within a matrix of oxidized metal with

<sup>60</sup>Co the predominant radionuclide". Several radionuclides in the metal oxide corrosion product

mixture include: <sup>58</sup>Co, <sup>60</sup>Co, <sup>54</sup>Mn, and <sup>59</sup>Fe with <sup>60</sup>Co being the predominant contributor to dose and

13 activity. These radionuclides are all associated with elements found in steel and alloys used in

reactor components. Other radionuclides may be present in trace amounts, but they generally are of

15 minimal internal dosimetry significance.

16 There were seven small Research and Test reactors operated at Hanford starting in 1944 with only

FFTF still in existence. Both external and internal exposures at these reactors were low (i.e. minimal

in most cases) and unique to the specific reactor. With the exception of routine tritium exposures

when working in the containment vessel at PRTR, external and internal exposures are primarily

20 associated with minor accidents.

21 External exposure at the PRTR was minimized as a result of the remote operation and the shielding.

22 Maintenance operations resulted in external exposure from activation and fission products. A high

extremity exposure occurred when a worker picked up an irradiated steel pin. Tritium (3H) oxide was

the principal internal exposure contaminant during normal operation. This was added into the whole

body dose (see Internal and External Dosimetry Sections). The reactor was shut down in 1969 after

an accident resulted in contamination in the reactor. A sample of the contamination showed the major

contaminant was <sup>95</sup>Zr/Nb. Other contaminants included <sup>60</sup>Co, <sup>103</sup>Ru, <sup>106</sup>Ru, <sup>106</sup>Rh, <sup>140</sup>Ba/La, <sup>141</sup>Ce,

<sup>144</sup>Ce. and <sup>144</sup>Pr.

Table A.1-1. Production reactors years of operation.

Reactor								
В	С	D	Dr	F	Н	KE	KW	N
9/1944-	11/1952-	12/1944-	10/1950-	2/1945-	10/1949-	2/1955-	12/1954	12/1963-
2/1968	4/1969	6/1967	12/1964	6/1965	4/1965	1/1971	-1970	1987

Table A.1-2. Radionuclides of concern for all production reactors.<sup>a</sup>

or an production reactors.						
As-76	I-135	Sr-91				
Ca-41	Mn-54	Sr-92				
Co-58	Mn-56	U-238				
Co-60	Na-24	Y-90				
Cr-51	Nb-97	Y-92				
Cu-64	Np-239	Y-93				
Fe-59	P-32	Zn-65				
Ga-72	Si-31	Zn-69				
I-133						

a. The composition and relative abundance are not known. These radionuclides represent 98% of radioactive materials in effluents. It should be noted that several of these are short-lived activation products (e.g. <sup>31</sup>Si, <sup>76</sup>As, etc) that would result in only limited, if any, exposure to workers.

Table A.1-3. Research and test reactors years of operation.

Reactor								
HTR	PCTR	TTR	PRTR	PRCF	HTLTR	FFTF		
1943- 1972	1954- 1970	1954-1978	1960- 1969	1962- 1976	1968- 1971	1980- 1994		

Table A.1-4. Radionuclides of concern for all research and test reactors.

<sup>103</sup> Ru	<sup>235</sup> U	<sup>35</sup> S
<sup>106</sup> Rh	<sup>238</sup> Pu	<sup>210</sup> Po
<sup>106</sup> Ru	<sup>238</sup> U	<sup>226</sup> Ra
<sup>140</sup> Ba/La	<sup>239</sup> Pu	<sup>233</sup> U
<sup>141</sup> Ce	<sup>3</sup> H	<sup>237</sup> Np
<sup>144</sup> Ce	<sup>60</sup> Co	<sup>240</sup> Pu
<sup>144</sup> Pr	<sup>95</sup> Zr/Nb	<sup>244</sup> Cm
<sup>233</sup> U	<sup>252</sup> Cf	

#### A.2 FUEL REPROCESSING FACILITIES

External exposures were primarily from high-energy betas and photons in the separations facilities associated with fission products (FP). Internal exposures, primarily associated with contamination incidents, could be due to FP and/or plutonium. The following mix of radionuclides ( $^{238}$ PU,  $^{239}$ PU,  $^{240}$ Pu, and  $^{241}$ Pu) comprises most plutonium mixtures at Hanford. The Hanford plutonium mixtures as shown in Tables A.2-3, A.2-4 and A.2-5 below were categorized by their weight percent of  $^{240}$ Pu (Carbaugh, 2003). When the production reactors were operating, the target mixture `was ~ 6%  $^{240}$ Pu (i.e. weapons grade). A special study in the 1980's indicated frequent-intermittent releases of plutonium in the workplaces at levels below detectability for normal air sampling. This resulted in < 10 mrem CEDE (Bihl, 1993; Lyon, et al, 1988; Lyon, et al, 1989).

The new lung model for internal Dosimetry uses absorption types. The new types are F, M, S for fast, moderate, and slow. Plutonium in nitrate form is M, which would apply to the separations plants up to the point when N cell was started at PUREX. Plutonium Oxide is classed as type S. This would apply to material calcined at either N cell at PUREX. Type S at PUREX would apply only to N cell, not the

	Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 31 of 38
--	----------------------------	-----------------	--------------------------------	---------------

- 1 PR Room. Contamination remaining in old glove boxes, hood exhaust ducts, HEPA and sand filters
- 2 and housings, etc., probably would be classed between M and S, but the default would be S. This is
- 3 because plutonium slowly oxides. Plutonium at 233-S was type M up until 1967 when the fire resulted
- 4 in the facility shutdown. The plutonium would be Type S by the time D&D was started at 233-S in the
- 5 1980s. It should be assumed after 1990 that all plutonium at Hanford would be class S because of
  - natural oxidation. Note: The default solubility classes should be used only when bioassay data is
- 7 inconclusive.

6

- The B Plant facilities were modified in 1968 to remove  $^{90}$ Sr and  $^{137}$ Cs from high-level wastes from the single and double-shell waste tanks. The purified  $^{90}$ Sr and  $^{137}$ Cs solutions were transferred to the 8
- 9
- 10 225-B Waste Encapsulation Storage Facility (see section 2.2.6). The 221-B operated from 1968 to
- 1978 in support of this new mission. Internal exposures from the operation were minimal due to the 11
- 12 remote operation. As a result of remote operation, external exposures to high-energy photons and
- beta particles resulting from the processing of large quantities of strontium and cesium were 13
- 14 minimized. The 108-B Facility was used for the extraction of Tritium (<sup>3</sup>H) for several years. Internal
- 15 exposure was related to tritium, which was added to whole body exposure (see External and Internal
- 16 Dosimetry Sections).
- 17 Internal exposures at U and UO<sub>3</sub> plants were due to the large quantities of uranium processed. The
- contaminant could be found ranging from soluble uranyl nitrate and UO<sub>3</sub> to insoluble UO<sub>2</sub> and U<sub>3</sub>O<sub>8</sub> 18
- 19 The inhalation class for Hanford uranium compounds, based on ICRP 66, is shown in Table A.3-5
- 20 below.

22

33 34

35

36

21 The years of operation and radionuclides of concern are shown in Tables A.2-1 and A.2-2 below.

Table A.2-1. Fuel reprocessing facilities years of operation.

Separation Facility									
В	T	REDOX	PUREX	U	UO₃	225-B	С	Tritium	
4/1945-	12/1944-	1/1952-	1/1956-	3/1952-	1/1952-	19UNK -	1949*-	8/1949 -	
10/1952(a)	Present (b)	12/1967©	121992 (d)	1/1958	1993(e)	Present	1967(f)	1955	

- In1968 B Plant started to remove Sr-90 and Cs-137 from high-level wastes; and shut down in 1978.
- The T-Plant discontinued reprocessing operation in March 1956 (\*) and was utilized as a Decontamination Facility; The 2706-T Annex was added in 1959.
- The 233-S facility located at REDOX started operation in 1957 and shutdown in 1967.
- Closed in 6/72 and reopened in 11/83.
- e. Shutdown in 1972 and opened again in 1983 (there were 17 start ups and shutdowns between 1984 and 1992)
- Started operations in 1952 (?) as REDOX Pilot Plant; 1954 started operations as PUREX Pilot Plant; 1962 started operation as Pilot Plant for recovery of Cs and Sr waste tanks NOTE: date for d has not been resolved.
- More than one date was found

UNK - No date found

Table A.2-2. Radionuclides of concern for all reprocessing facilities.

<sup>103</sup> Ru	<sup>235</sup> U
<sup>106</sup> Ru	<sup>237</sup> Np
<sup>131</sup>	<sup>238</sup> U
<sup>137</sup> Cs	<sup>239</sup> Pu
<sup>140</sup> Ba/La	<sup>241</sup> Am
<sup>141</sup> Ce	<sup>3</sup> H
<sup>144</sup> Ce	<sup>60</sup> Co
<sup>233</sup> U	<sup>90</sup> Sr

Ellective Date: 10/02/2003   Revision No. 00     Document No. ORAO 1-1 ND3-0000-2   Page 32 of 30	Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 32 of 38
---	----------------------------	-----------------	--------------------------------	---------------

1 Table A.2-3. Activity composition of Hanford reference weapons-grade plutonium mixture.

Mixture	1						
designation:	Fresh	5-Year	10-Year	15-Year	20-Year	25-Year	30-Year
Years of aging <sup>a</sup> :	0	5	10	15	20	25	30
Specific activity in							
mixture (Ci/g)							
<sup>238</sup> Pu	8.56E-03	8.23E-03	7.91E-03	7.60E-03	7.31E-03	7.03E-03	6.75E-03
<sup>239</sup> Pu	5.77E-02						
<sup>240</sup> Pu	1.36E-02						
<sup>241</sup> Pu	8.24E-01	6.48E-01	5.09E-01	4.00E-01	3.15E-01	2.48E-01	1.95E-01
<sup>242</sup> Pu	1.97E-06						
<sup>241</sup> Am	0	5.83E-03	1.04E-02	1.39E-02	1.66E-02	1.87E-02	2.03E-02
<sup>239+240</sup> Pu	7.13E-02	7.13E-02	7.13E-02	7.13E-02	7.12E-02	7.12E-02	7.12E-02
Pu-alpha	7.99E-02	7.95E-02	7.92E-02	7.89E-02	7.85E-02	7.83E-02	7.80E-02
Total alpha	7.99E-02	8.53E-02	8.96E-02	9.28E-02	9.52E-02	9.70E-02	9.83E-02
Activity ratios							
<sup>239+240</sup> Pu: <sup>241</sup> Am	NA	12.2	6.87	5.13	4.28	3.80	3.50
<sup>239+240</sup> Pu: <sup>238</sup> Pu	8.33	8.67	9.01	9.38	9.74	10.1	10.5
<sup>241</sup> Pu: <sup>239+240</sup> Pu	11.6	9.09	7.15	5.62	4.42	3.48	2.73
Pu alpha: <sup>239+240</sup> Pu	1.12	1.20	1.26	1.30	1.34	1.36	1.38
Pu alpha: 238Pu	9.33	9.66	10.0	10.4	10.7	11.1	11.6
Pu alpha: <sup>241</sup> Am	NA	14.6	8.63	6.67	5.72	5.18	4.84
<sup>241</sup> Pu: Pu alpha	10.3	8.15	6.43	5.07	4.01	3.17	2.50

<sup>2</sup> a. Time since separation of <sup>241</sup>Am from the Pu mix.

3 Table A.2-4. Activity composition of Hanford reference fuel-grade plutonium mixture.

Mixture							
designation:	Fresh	5-Year	10-Year	15-Year	20-Year	25-Year	30-Year
Years of aging <sup>a</sup> :	0	5	10	15	20	25	30
Specific activity in							
mixture (Ci/g)							
<sup>238</sup> Pu	1.71E-02	1.64E-02	1.58E-02	1.52E-02	1.46E-02	1.40E-02	1.35E-02
<sup>239</sup> Pu	5.26E-02	5.26E-02	5.26E-02	5.26E-02	5.26E-02	5.26E-02	5.25E-02
<sup>240</sup> Pu	2.72E-02	2.72E-02	2.72E-02	2.72E-02	2.72E-02	2.71E-02	2.71E-02
<sup>241</sup> Pu	3.09E+00	2.43E+00	1.91E+00	1.50E+00	1.18E+00	9.29E-01	7.30E-01
<sup>242</sup> Pu	3.93E-06						
<sup>241</sup> Am	0	2.19E-02	3.89E-02	5.22E-02	6.24E-02	7.03E-02	7.63E-02
<sup>239+240</sup> Pu	7.98E-02	7.98E-02	7.98E-02	7.97E-02	7.97E-02	7.97E-02	7.97E-02
Pu-alpha	9.69E-02	9.62E-02	9.56E-02	9.49E-02	9.43E-02	9.37E-02	9.32E-02
Total alpha	9.69E-02	1.18E-01	1.35E-01	1.47E-01	1.57E-01	1.64E-01	1.69E-01
Activity ratios							
<sup>239+240</sup> Pu: <sup>241</sup> Am	NA	3.64	2.05	1.53	1.28	1.13	1.04
<sup>239+240</sup> Pu: <sup>238</sup> Pu	4.67	4.86	5.05	5.24	5.46	5.69	5.90
<sup>241</sup> Pu: <sup>239+240</sup> Pu	3.87	3.05	2.40	1.88	1.48	1.17	9.16
Pu alpha: <sup>239+240</sup> Pu	1.21	1.21	1.20	1.19	1.18	1.18	1.17
Pu alpha: <sup>238</sup> Pu	5.67	5.87	6.05	6.24	6.46	6.69	6.90
Pu alpha:241Am	NA	4.39	2.46	1.82	1.51	1.33	1.22
<sup>241</sup> Pu: Pu alpha	31.9	25.3	20.0	15.8	12.5	9.91	7.83

a. Time since separation of the <sup>241</sup>Am from the Pu mix.

	Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 33 of 38
--	----------------------------	-----------------	--------------------------------	---------------

## Table A.2-5. Activity composition of Hanford reference commercial power fuel-grade plutonium mixture.

Mixture designation:	Fresh	5-Year	10-Year	15-Year	20-Year	25-Year	30-Year
Years of aging <sup>a</sup> :	0	5	10	15	20	25	30
Specific activity in mixture (Ci/g)				-	-		
<sup>238</sup> Pu	1.71E-01	1.64E-01	1.58E-01	1.52E-01	1.46E-01	1.40E-01	1.35E-01
<sup>239</sup> Pu	3.41E-02						
<sup>240</sup> Pu	5.90E-02	5.89E-02	5.89E-02	5.89E-02	5.89E-02	5.88E-02	5.88E-02
<sup>241</sup> Pu	1.34E+01	1.05E+01	8.28E+00	6.51E+00	5.12E+00	4.03E+00	3.17E+00
<sup>242</sup> Pu	1.97E-04						
<sup>241</sup> Am	0	9.49E-02	1.69E-01	2.26E-01	2.79E-01	3.04E-01	3.31E-01
<sup>239+240</sup> Pu	9.31E-02	9.31E-02	9.30E-02	9.30E-02	9.29E-02	9.29E-02	9.29E-02
Pu-alpha	2.65E-01	2.58E-01	2.52E-01	2.45E-01	2.39E-01	2.34E-01	2.28E-01
Total alpha	2.65E-01	3.53E-01	4.20E-01	4.71E-01	5.10E-01	5.38E-01	5.59E-01
Activity Ratios							
<sup>239+240</sup> Pu: <sup>241</sup> Am	NA	0.981	0.551	0.411	0.344	0.305	0.281
<sup>239+240</sup> Pu: <sup>238</sup> Pu	0.544	0.568	0.589	0.612	0.636	0.664	0.688
<sup>241</sup> Pu: <sup>239+240</sup> Pu	144	113	89.1	70.0	55.1	43.3	34.1
Pu alpha: <sup>239+240</sup> Pu	2.85	2.77	2.71	2.63	2.57	2.52	2.45
Pu alpha: <sup>238</sup> Pu	1.55	1.57	1.59	1.61	1.64	1.67	1.69
Pu alpha: <sup>241</sup> Am	NA	2.72	1.49	1.08	0.857	0.770	0.689
<sup>241</sup> Pu: Pu alpha	50.6	40.7	32.9	26.6	21.4	17.2	13.9

a. Time since separation of the <sup>241</sup>Am from the Pu mix.

### A.3 FUEL FABRICATION FACILITIES

External exposures were related to betas and photons associated with uranium. Due to the pyrophoric nature of uranium turnings and chips, internal exposure was related primarily to inhalation of uranium. A pressurization of one of the sealed metal storage cans resulted in the spread of plutonium contamination and the subsequent shut down of the building until cleanup. The years of operation and radionuclides of concern are shown in Tables A.3-1 and A.3-2 below. The radiological characteristics of Hanford uranium mixtures are shown in Table A.3-3 and the impurities in recycled Hanford uranium are shown in Table A.3-4. The inhalation class for Hanford uranium compounds is shown in Table A.3-5. Note: The default solubility classes should be used only when bioassay data is inconclusive.

Table A.3-1. Fuel fabrication facilities years of operation.

	_	Fuel fabrication		
313	314	333	303 Facilities	306
3/1944 –1/1971	7/1944 -1971	1961 -1988	1944 - Present	5/1957 -1984

Table A.3-2. Radionuclides of concern for all fuel fabrication and storage facilities.

1 abic 7 2. 1	tadionaciaes c					
<sup>241</sup> Am	<sup>237</sup> Np	<sup>238</sup> Pu	<sup>239</sup> Pu	<sup>232</sup> Th	<sup>235</sup> U	<sup>238</sup> U

Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 34 of 38

Table A.3-3. Radiological characteristics of Hanford uranium mixtures.

	Uranium mixture						
Weight percentage <sup>a,b</sup>	Natural (NU)	Depleted (DU)	Recycled (RU)	Commercial fuel (CF)			
<sup>234</sup> U	0.0057	0.0005	0.0082	0.0300			
<sup>235</sup> U	0.7204	0.2500	0.9700	2.9600			
<sup>236</sup> U	Negligible	Negligible	0.0680	Negligible			
<sup>238</sup> U	99.2739	99.7500	98.9500	97.0100			
Specific constitue	ent activity in m	ixture (uCi/g, nC	i/mg, or pCi/ug	Ċ			
. 234U	0.3563	0.0313	0.5125	1.8750			
<sup>235</sup> U	0.0156	0.0054	0.0210	0.0639			
<sup>236</sup> U	Negligible	Negligible	0.0440	Negligible			
<sup>238</sup> U	0.3336	0.3352	0.3325	0.3260			
Total	0.7054	0.3718	0.9099	2.2649			
Specific constitue	ent activity in m	ixture (dpm/ug) <sup>c</sup>					
<sup>234</sup> U	0.7909	0.0694	1.1378	4.1625			
<sup>235</sup> U	0.0345	0.0120	0.0465	0.1419			
<sup>236</sup> U	Negligible	Negligible	0.0977	Negligible			
<sup>238</sup> U	0.7405	0.7441	0.7381	0.7236			
Total	1.5659	0.8254	2.0200	5.0281			
Constituent fracti	on of total uran	ium activity in m	ixture				
<sup>234</sup> U	0.5051	0.0840	0.5632	0.8279			
<sup>235</sup> U	0.0221	0.0145	0.0230	0.0282			
<sup>236</sup> U	Negligible	Negligible	0.0484	Negligible			
<sup>238</sup> U	0.4729	0.9014	0.3654	0.1439			
Total	1.0000	1.0000	1.0000	1.0000			

- a. NU, DU, and CF data from Rich et al, 1988.
- b. RU data based on average of data presented by Sula, et al, 1991.
- c. Can be used to represent specific alpha activity in the mixture as well.

Table A.3-4. Impurities in recycled uranium at Hanford.

Constituent	Maximum allowed <sup>a</sup>	Observed range <sup>b</sup>	Reference level <sup>c</sup>
Plutonium	10 ppb U	<1 - 2 ppb U	0.4 nCi Pu-alpha/gU
Neptunium	Not established	0.04-0.16 ppm U	0.4 nCi <sup>237</sup> Np/g U
Thorium	750 ppm U	8 - 10 ppm U	5 pCi <sup>232</sup> Th/g U
<sup>99</sup> Tc	Not established	3 - 4 ppm U	0.2 uCi <sup>99</sup> Tc/g U
<sup>103,106</sup> Ru	<20 uCi/lb U	<6 uCi/lb U	40 nCi <sup>106</sup> Ru/g U
<sup>95</sup> ZrNb	<10 uCi/lb U	<4 uCi/lb U	20 nCi <sup>95</sup> ZrNb/g U
Other gamma emitters excluding <sup>99</sup> Tc	<2 uCi/lb U	0.09 0.75 uCi/lbU	Negligible

- a. From UO3 Plant operating specifications, OSD-U-185-0001 (Thompson 1986).
- b. From analysis of uranium lots 88-1, 88-2, 88-3 that was processed in 1988, and lots 93-01, 93-02, 93-03, 93-04, and 93-05, processed in 1993.
- c. A reference level is chosen for determining bioassay-monitoring needs and for use as an initial assumption in evaluating intakes. The use of the reference levels is expected to result in a slight overestimate of dose compared to levels actually observed in 1988.

3

5

1

Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 35 of 38

Table A.3-5. Inhalation class for Hanford uranium compounds.

ICRP 30 inhalation class from lung fluid studies	Compound and location	Recommended ICRP 66 lung absorption type
80% D	Hanford UO <sub>3</sub> Plant smear sample dissolution study in 1984 <sup>a</sup> ,	F
20% W	(UO <sub>3</sub> powder)	
10% D	Hanford 303-M Building air sample dissolution study <sup>b</sup> (300 Area	S
90% Y	Uranium Fuel Production Facilities)	
29% D	Hanford 333 Building air sample dissolution study <sup>b</sup> (300 Area	S
71% Y	Uranium Fuel Production Facilities)	
20% D	Hanford 306-W Building Machine Shop air sample dissolution	S
80% Y	study <sup>b</sup>	
	Uranyl nitrate at Purex or UO3 Plant	F
	UCl <sub>4</sub> or U carbonate (assumed form after discharge to the soil)	M <sup>c</sup>

- Sula, Bihl, and Carbaugh (1989).
- 2 b. Fisher, (1986).

1

- 4 Cooke and Holt 1974.
- 5 d. Note: The default solubility classes should be used only when bioassay data is inconclusive.

#### 6 PLUTONIUM FINISHING FACILITIES **A.4**

- 7 Although relatively few Hanford personnel were involved in plutonium finishing, these facilities
- provided the majority of personnel external exposures to neutron radiation. As production increased, 8
- 9 ten-inch thick water-filled walls were installed to reduce worker exposure to neutrons. Special lead-
- filled gloves were installed to reduce extremity exposure. Worker external exposure in the vault 10
- 11 rooms was due to low-energy photons and neutrons that occurred during periodic inventory and
- 12 inspection activities.
- 13 Internal exposures in the operating areas were related primarily to contamination incidents involving
- 14 americium and plutonium since airflow patterns were designed to control the flow from areas of lower
- air contamination potential to higher. Maintenance and clean-up operations were conducted in 15
- protective clothing including respiratory protection. Exposures occurred by inhalation, absorption and 16
- 17 injection (i.e. wound sites). Internal exposure in the vault areas was minimal since there were no
- routine activities that involved opening the storage containers. Internal exposure would have been a 18
- concern in the event of an incident that breached the containment. 19
- 20 In Feb. 1960, RECUPLEX was temporarily shut down to permit an extensive cleanup of hoods and
- 21 operating equipment. A criticality accident that occurred in the RECUPLEX facility in April 1962
- 22 resulted in high external radiation exposures and in widespread contamination throughout the
- 23 RECUPLEX room.
- 24 The new lung model for internal Dosimetry uses absorption types. The new types are F, M, S for fast,
- 25 moderate, and slow. Plutonium in nitrate form is M, which would apply to the plutonium finishing
- plants where plutonium nitrate has been involved (e.g. RECUPLEX, 231-Z, etc.). Plutonium Oxide 26 that is classed as type S, would apply to material calcined at the RMC line at PFP. Contamination 27
- remaining in old glove boxes, hood exhaust ducts, HEPA and sand filters and housings, etc., probably 28
- would be classed between M and S, but the default would be S. This is because plutonium slowly 29 30 oxides. It should be assumed after 1990 that all plutonium at Hanford would be class S because of
- natural oxidation. In a study performed in the early 1990's of the isotopic distribution of plutonium at 31
- PFP, it was stated there were ~3.7 million grams of plutonium with the <sup>240</sup>Pu content ranging from 4% 32
- to >19% (Crowe, Szempruch 1994). Note: The default solubility classes should be used only when 33
- 34 bioassay data is inclusive.

Effective Date: 10/02/2003	Revision No. 00	Document No. ORAUT-TKBS-0006-2	Page 36 of 38
----------------------------	-----------------	--------------------------------	---------------

- 1 The years of operation and the radionuclides of concern are listed in Tables A.4-1 and A.4-2 below.
- 2 The activity composition for Hanford reference plutonium mixtures is shown in Tables A.2-3, A.2-4,
- 3 and A.2-5 above.

4

5678910112 1121314

15

16

25

26

27

#### Table A.4-1. Plutonium finishing facilities years of operation.

	Facility/process							
231-Z	232-Z	2345Z RG	2345Z RMA	2345Z RMC	2345Z RECUPLEX	2345Z Storage vault	236-Z	242-Z
1/1945 - 19UNK(	1/1962 -	7/1949 -	3/1952 - 1984(b)	10/1960	7/1955 – 1/1962	1949 -Present	5/1964 - 4/1976(	1963 - 1976(e)
a)	1973	1957		1989(c)			d)	

- In 1956 the mission changed to plutonium metallurgy development: In 19UNK <sup>233</sup>U metallurgy studies were undertaken.
- In 1964 line shutdown: In 1967 a glove box was reactivated; In 1968, Tasks I-III were cleaned out and reactivated; In 1984 it was decided to keep the RMA on standby.
- c. In 1962 ten-inch thick water-filled shielding tanks were added to substantially reduce operator exposure to neutrons; Several safety improvements made in 1963 and 1964; Fabrication of pits removed from line in 1966. Shutdown in 1976 as a result of explosion in 242-Z; The RMC line restarted in 1985; Shut down in 1989.
- d. In 12/1975 it was shutdown for upgrades; Restarted in 1976; Shut down in 4/1976 as a result of explosion in 242-Z.
- e. In 1969 changed from batch to continuous process; In 4/1976 shut down because of strike; In 8/1976 restarted; Shut down in 8/1976 as a result of explosion in americium recovery area.

#### Table A 4-2 Radionuclides of concern for plutonium finishing facilities

			p.o.to.					
<sup>233</sup> U	<sup>237</sup> Np	<sup>238</sup> Pu	<sup>239</sup> Pu	<sup>240</sup> Pu	<sup>241</sup> Pu	<sup>242</sup> Pu	<sup>241</sup> Am	

#### **A.5** RESEARCH AND DEVELOPMENT FACILITIES

- 17 The 21-major Research, Development, and Testing Facilities at Hanford were located in the 100, 200
- and 300 Areas. Construction of these started in 1944 with the last one completed in 1977. These 18
- 19 facilities were built to support the development and testing of new processes, materials, and
- 20 equipment. In some instances the facilities were used for several different purposes throughout their
- 21 operating life. Therefore, the potential exposures are dependent on the processes involved and the
- 22 mission/process at any given time. See sections 2.5.1 through 2.5.21 for discussion on internal and
- 23 external exposure potential at specific facilities. .The years of operation and the radionuclides of
- concern are listed in Tables A.5-1, A.5-2, and A.5-3 below. 24

#### Table A.5-1. 100 and 200 Area research and development facilities years of operation.

Facility/process						
108-F	120	209-E	222-B	222-S	222-T	
1949 -1977	4/1950 – 11/1951	7/1961 -19860*	1945 -1975	1949 -present	1944 -1986**	

<sup>\*</sup>Only decade date found

#### 28 Table A.5-2. 300 Area research and development facilities years of operation.

	Facility/process					
308	318	320	321	324	325	326
1960 -1990* <sup>a</sup>	1983 – Present <sup>b</sup>	1966 - Present	1944 -1988 <sup>c</sup>	1966 - Present	1953 – Present <sup>d</sup>	1953 - Present

<sup>\*\*</sup>More than on date found

1

21

23

24

25

26

27

28 29

### Table A.5-3. 300 Area research and development facilities years of operation (continued).

Facility/process							
327	329	331	3706	3730	3732	3741	3745
1953 -	1952 -	1972 -	1945 -	1949 -	1949 -	1944 -	10/1944 -
1987	Present	Present	late1960's <sup>e</sup>	1981	1970	1956	1983 <sup>f</sup>

- a. In mid 1960's PRTR fuel work was terminated; Np-Al allow fuel elements produced in late 1960's; High bay area added in 1971; From 1977-1991 FFTF fuel elements were produced; The 308A annex was added in 1979; Triga reactor was installed in the late 1970's.
- b. The HTLTR reactor commenced operation in the 318 building in 1967; The reactor was shut down in 19UNK; The reactor was removed in the early 1980's; The calibration facility commenced operation in 1983; Major additions were added in 1986, 1987, and 1989.
- The 321 separation building started in 1944; In late 1944 work with small amounts of irradiated materials to conduct separations experiments and to study decontamination factors; in1949 a cold test of REDOX process was performed; A cold test of the PUREX process was tested in 1953.
- d. The 325-A hot cell wing was added in 1959\*; Pm-147 heat sources manufactured in 1966; Po-210 work started in 6/1972 and ended in 1970\*. For use with the demonstration of the Waste Vitrification Process for commercial wastes.
- e. Most of the radiation laboratories were removed in 1954; Work with radioactive materials discontinued in late 1960's; building converted to offices in the 1970's and still in use in the early 1990's.
- f. The 3745-B annex that housed a 4 MV Positive Ion Accelerator started operation in 1955; The 3745-A annex that housed a 2 MV Negative Ion Accelerator started operation in 1950\*; The calibrations operations were transferred to the 318 building in 1983; The building is being used as offices.

Table A.5-4. Radionuclides of concern for all 100, 200, and 300 Area research and development facilities.

acvelopinent laciniles.				
<sup>14</sup> C	<sup>147</sup> Pm			
<sup>144</sup> Ce	<sup>238</sup> Pu			
<sup>60</sup> Co	<sup>239</sup> Pu			
<sup>137</sup> Cs	<sup>103</sup> Ru			
<sup>64</sup> Cu	<sup>106</sup> Ru			
FP	<sup>90</sup> Sr			
<sup>131</sup>	<sup>238</sup> U			
<sup>235</sup> U	<sup>90</sup> Y			

#### 22 A.6 WASTE FACILITIES

External exposure is related to high-energy beta and photon radiations from the fission products stored in the tanks. Under normal conditions shielding, distance and time helped keep personnel external exposures at a low level. Leaks of high-level wastes that could result in unusual or unplanned external exposures were documented in incident or accident reports. In1994, data was included in (Boomer, et al 1994) on tank waste radionuclide inventory. The data from that report are included in Table A.6-3. Internal exposures to FP were controlled through the use of respiratory protection.

- A mining operation to remove an estimated 45 kg of plutonium from the Z-9 trench was initiated in Aug. 1976 and was completed in July 1978. The principal internal exposure potential was related to 32 239Pu contamination, most of which occurred in the soil packaging glove box. Since the waste site 33 was used only for plutonium, the external exposure potential during the mining operation was minimal.
- 34 The years of operation and radionuclides of concern are shown in Tables A.6-1 and A.6-2 below.

### Table A.6-1. Waste facilities years of operation.

	Facility/Process							
Waste Tanks	Z-9 Trench Facility	241-Z	242 Evaporator Facilities	Exhaust Filtration Facilities	340 Waste Complex			
1944 -Present	1955 -1978	1949 -1973	1951 -Present	1947 -19UNK	1954 -Present			

Table A.6-2. Radionuclides of concern for all waste facilities.

<sup>141</sup> Ce	<sup>238</sup> Pu				
<sup>144</sup> Ce	<sup>239</sup> Pu				
<sup>60</sup> Co	<sup>103</sup> Ru				
<sup>137</sup> Cs	<sup>106</sup> Ru				
FP	<sup>90</sup> Sr				
<sup>131</sup>	<sup>90</sup> Y				
<sup>147</sup> Pm					

### 5 Table A.6-3. Tank waste radionuclide inventory.

Mega curies of	Liquid con	nponents	Solid components	
radioactive specie	Double-shell tanks	Single-shell tanks	Double-shell tanks	Single-shell tanks
<sup>137</sup> Cs and <sup>137</sup> Ba	6.40 E+01	2.53 E+01	2.33 E+00	8.45 E+00
<sup>90</sup> Sr and <sup>90</sup> Y	3.93 E+00	1.14 E+01	2.17 E+01	1.13 E+02
<sup>99</sup> TC	2.28 E-02	7.82 E-03	1.35 E-03	7.82 E-03
<sup>241</sup> Am	1.45 E-02	4.70 E-03	7.97 E-02	4.23 E-02
<sup>237</sup> Np	1.64 E-05	3.30 E-06	1.92 E-05	2.97 E-05
Pu	3.84 E-03	5.50 E-04	6.80 E-03	2.69 E-02
TRU	1.93 E-02	5.25 E-03	9.10 E-02	6.92 E-02

1

2